METROPOLITAN COAL LONGWALL 304

LAND MANAGEMENT PLAN

















METROPOLITAN COAL

LONGWALL 304 LAND MANAGEMENT PLAN

Revision Status Register

Section/Page/ Annexure	Revision Number	Amendment/Addition	Distribution	DP&E Approval Date
All	LMP-R01-A	Original – Draft for Consultation	WaterNSW, DP&E	-
Sections 4.1 and 4.3	LMP-R01-B	Minor corrections	WaterNSW, DP&E	-

April 2019

TABLE OF CONTENTS

Section				<u>Page</u>
1	INTROE	DUCTION	ı	1
	1.1	PURPO	OSE AND SCOPE	1
	1.2	STRUC	CTURE OF THE LAND MANAGEMENT PLAN	1
2	LAND M	1ANAGEI	MENT PLAN REVIEW AND UPDATE	5
	2.1	DISTRI	BUTION REGISTER	5
3	STATU	TORY RE	EQUIREMENTS	6
	3.1	ENVIR	ONMENTAL PLANNING & ASSESSMENT ACT APPROVAL	6
	3.2	LICEN	CES, PERMITS AND LEASES	8
	3.3	OTHER	RLEGISLATION	8
4	REVISE	D ASSE	SSMENT OF POTENTIAL ENVIRONMENTAL CONSEQUENCES	9
	4.1	LONG	VALL 304 EXTRACTION LAYOUT	9
	4.2	RELEV	ANT INFORMATION OBTAINED SINCE PROJECT APPROVAL	9
	4.3	ENVIR	ONMENTAL RISK ASSESSMENT	11
	4.4	CLIFFS	S AND OVERHANGS	13
		4.4.1	Revised Subsidence Predictions	14
		4.4.2	· · · · · · · · · · · · · · · · · · ·	
		07555	Environmental Consequences	14
	4.5		SLOPES	15
		4.5.1		15
		4.5.2	Revised Assessment of Potential Subsidence Impacts and Environmental Consequences	16
	4.6	LAND I	N GENERAL	16
		4.6.1	Revised Subsidence Predictions	17
		4.6.2	Revised Assessment of Potential Subsidence Impacts and	
			Environmental Consequences	17
5	PERFO	RMANCE	MEASURES AND INDICATORS	17
	5.1	CLIFFS	S AND OVERHANGS	17
	5.2	STEEP	SLOPES AND LAND IN GENERAL	19
6	BASELI	NE DATA	A	19
	6.1	CLIFFS	S AND OVERHANGS	19
	6.2	STEEP	SLOPES AND LAND IN GENERAL	20
7	MONITO	ORING		20
	7.1	SUBSII	DENCE PARAMETERS	20
	7.2	SUBSII	DENCE IMPACTS	21
		7.2.1	Cliffs and Overhangs	21
		7.2.2	Steep Slopes and Land in General	22
	7.3	TRIGG	ER ACTION RESPONSE PLAN	23

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page i		
Document ID: Land Management Plan		

TABLE OF CONTENTS (continued)

8	MANAGEMENT MEASURES	23
9	CONTINGENCY PLAN	27
10	FUTURE EXTRACTION PLANS	29
11	ANNUAL REVIEW AND IMPROVEMENT OF ENVIRONMENTAL PERFORMANCE	29
12	INCIDENTS	30
13	COMPLAINTS	30
14	NON-COMPLIANCES WITH STATUTORY REQUIREMENTS	31
15	REFERENCES	31

LIST OF TABLES

Table 1	Management Plan Requirements
Table 2	Revised Subsidence Predictions for Cliffs and Overhangs
Table 3	Maximum Predicted Incremental Conventional Subsidence, Tilt and Curvature Resulting from Longwall 304 Extraction
Table 4	Comparison of Maximum Predicted Conventional Subsidence Parameters based on the Preferred Project Layout and the Extraction Plan Layout
Table 5	Length of Cliffs and Overhangs within the Project Underground Mining Area
Table 6	Trigger Action Response Plan - Cliffs and Overhangs, Steep Slopes and Land in General
Table 7	Potential Management Measures – Cliffs and Overhangs
Table 8	Potential Management Measures – Steep Slopes and Land in General

LIST OF FIGURES

Figure 1	Longwall 304 and Project Underground Mining Area
Figure 2	Cliffs and Overhangs, Steep Slopes and Land in General within the Project Underground Mining Area and Surrounds
Figure 3	Environmental Management Structure
Figure 4	Cliffs and Overhangs, Steep Slopes and Land in General within 600 m of Longwall 304 and Surrounds

LIST OF APPENDICES

Appendix 1	Baseline Mapping and Photographs – Cliffs and Overhangs
Appendix 2	Land Management Plan – Subsidence Impact Register and Assessment Form
Appendix 3	Contingency Plan Check List

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B		Page ii	
Document ID: Land Management Plan			

1 INTRODUCTION

Metropolitan Coal is a wholly owned subsidiary of Peabody Energy Australia Pty Ltd (Peabody). Metropolitan Coal was granted approval for the Metropolitan Coal Project (the Project) under section 75J of the New South Wales (NSW) *Environmental Planning and Assessment Act, 1979* (EP&A Act) on 22 June 2009. A copy of the Project Approval is available on the Peabody website (http://www.peabodyenergy.com).

The Project comprises the continuation, upgrade and extension of underground coal mining operations (Longwalls 20-27 and Longwalls 301-317) and surface facilities at the Metropolitan Coal Mine (Figure 1). Longwall 304 is situated to the west of Longwalls 301-303, and defines the next mining sub-domain within the Project underground mining area (Figures 1 and 2). Longwalls 305 on will be subject to future Extraction Plans.

1.1 PURPOSE AND SCOPE

In accordance with Condition 6, Schedule 3 of the Project Approval, this Land Management Plan (LMP) has been prepared as a component of the Metropolitan Coal Longwall 304 Extraction Plan to manage the potential environmental consequences of the Extraction Plan on cliffs and overhangs, steep slopes and land in general.

The relationship of this LMP to the Metropolitan Coal Environmental Management Structure and to the Metropolitan Coal Longwall 304 Extraction Plan is shown on Figure 3.

This LMP includes post-mining monitoring and management of cliffs and overhangs, steep slopes and land in general for Longwalls 20-22, 23-27 and 301-303, subject to the previously approved Metropolitan Coal Longwalls 301-303 LMP. Consistent with the recommended approach in the NSW Department of Planning & Environment (DP&E) and NSW Division of Resources and Energy (DRE) (2015) *Guidelines for the Preparation of Extraction Plans*, the Metropolitan Coal Longwalls 301-303 LMP will be superseded by this document following the completion of Longwall 303.

In accordance with Condition 6, Schedule 3 of the Project Approval, this LMP has been prepared by Metropolitan Coal with assistance from Resource Strategies and Mine Subsidence Engineering Consultants (MSEC).


1.2 STRUCTURE OF THE LAND MANAGEMENT PLAN

The remainder of this LMP is structured as follows:

Section 2:	Describes the	 	-t + -;- N 1 D

- Section 3: Outlines the statutory requirements applicable to this LMP.
- Section 4: Provides a revised assessment of the potential subsidence impacts and environmental consequences for Longwall 304.
- Section 5: Details the performance measures and indicators that will be used to assess the Project.
- Section 6: Provides the detailed baseline data.
- Section 7: Describes the monitoring program and Trigger Action Response Plan (TARP) for cliffs and overhangs, steep slopes and land in general.
- Section 8: Describes the management measures that will be implemented.

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B		Page 1	
Document ID: Land Management Plan			




Mining Lease Boundary
Woronora Special Area
Railway
Project Underground Mining Area
Longwalls 20-27 and 301-317
Longwall 304 Secondary Extraction
35° Angle of Draw and/or Predicted
20 mm Subsidence Contour
600 m from Secondary Extraction of
Longwall 304
Woronora Notification Area
Existing Underground Access Drive (Main Drift)

Source: Land and Property Information (2015); Department of Industry (2015); Metropolitan Coal (2019); MSEC (2019)



METROPOLITAN COAL

Longwall 304 and Project Underground Mining Area



LEGEND

Mining Lease Boundary
Railway

Project Underground Mining Area
Longwalls 20-27 and 301-317
Longwall 304 Secondary Extraction
35° Angle of Draw and/or Predicted

20 mm Subsidence Contour

600 m from Secondary Extraction of Longwall 304

---- Existing Underground Access Drive (Main Drift)


Cliffs and Overhangs
Steep Slopes (Project Approval)
Steep Slopes (Project Environmental Assessment)

Source: Land and Property Information (2015); Date of Aerial Photography 1998; Department of Industry (2015); Metropolitan Coal (2019); MSEC (2008; 2019)

<u>Peabody</u>

METROPOLITAN COAL

Cliffs and Overhangs, Steep Slopes and Land in General within the Project Underground Mining Area and Surrounds





METROPOLITAN COAL

Environmental Management Structure

Section 9: Provides a Contingency Plan to manage any unpredicted impacts and their consequences.

Section 10: Describes the program to collect baseline data for future Extraction Plans.

Section 11: Describes the annual review and improvement of environmental performance.

Section 12: Outlines the management and reporting of incidents.

Section 13: Outlines the management and reporting of complaints.

Section 14: Outlines the management and reporting of non-compliances with statutory

requirements.

Section 15: Lists the references cited in this LMP.

2 LAND MANAGEMENT PLAN REVIEW AND UPDATE

In accordance with Condition 4, Schedule 7 of the Project Approval, this LMP will be reviewed within three months of the submission of:

- an audit under Condition 8, Schedule 7;
- an incident report under Condition 6, Schedule 7;
- an annual review under Condition 3, Schedule 7; and

if necessary, revised to the satisfaction of the Director-General (now Secretary) of the DP&E to ensure this LMP is updated on a regular basis and to incorporate any recommended measures to improve environmental performance.

This LMP will also be reviewed within three months of approval of any Project modification and if necessary, revised to the satisfaction of the DP&E.

The revision status of this LMP is indicated on the title page of each copy. The distribution register for controlled copies of this LMP is described in Section 2.1.

2.1 DISTRIBUTION REGISTER

In accordance with Condition 10, Schedule 7 of the Project Approval 'Access to Information', Metropolitan Coal will make this LMP publicly available on the Peabody website. A hard copy of this LMP will also be maintained at the Metropolitan Coal Mine.

Metropolitan Coal recognises that various regulators have different distribution requirements, both in relation to whom documents should be sent and in what format.

An Environmental Management Plan and Monitoring Program Distribution Register has been established in consultation with the relevant agencies and infrastructure owners that indicates:

- to whom the Metropolitan Coal plans and programs, such as this LMP, will be distributed;
- the format (i.e. electronic or hard copy) of distribution; and
- the format of revision notification.

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B		Page 5	
Document ID: Land Management Plan			

Metropolitan Coal will make the Distribution Register publicly available on the Peabody website.

Metropolitan Coal will be responsible for maintaining the Distribution Register and for ensuring that the notification of revisions is sent by email or post as appropriate.

In addition, Metropolitan Coal employees with local computer network access will be able to view the controlled electronic version of this LMP on the Metropolitan Coal local area network. Metropolitan Coal will not be responsible for maintaining uncontrolled copies beyond ensuring the most recent version is maintained on Metropolitan Coal's computer system and the Peabody website.

3 STATUTORY REQUIREMENTS

Metropolitan Coal's statutory obligations are contained in:

- (i) the conditions of the Project Approval;
- (ii) relevant licences and permits, including conditions attached to mining leases; and
- (iii) other relevant legislation.

These are described below.

3.1 ENVIRONMENTAL PLANNING & ASSESSMENT ACT APPROVAL

Condition 6(f), Schedule 3 of the Project Approval requires the preparation of a LMP as a component of Extraction Plan(s) for second workings. Condition 6(f), Schedule 3 states:

SECOND WORKINGS

Extraction Plan

6. The Proponent shall prepare and implement an Extraction Plan for all second workings in the mining area to the satisfaction of the Director-General. This plan must:

(f) include a:

...

• Land Management Plan, which has been prepared in consultation with the SCA^[1], to manage the potential environmental consequences of the Extraction Plan on cliffs, overhangs, steep slopes and land in general;

In addition, Condition 2, Schedule 7 and Condition 7, Schedule 3 of the Project Approval outline management plan requirements that are applicable to the preparation of this LMP. Table 1 indicates where each component of the conditions is addressed within this LMP.

The Sydney Catchment Authority (SCA) is now WaterNSW.

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B Page 6			
Document ID: Land Management Plan			

Table 1 Management Plan Requirements

		Project Approval Condition	LMP Section
Со	nditi	on 2, Schedule 7	
2.	app	Proponent shall ensure that the management plans required under this proval are prepared in accordance with any relevant guidelines, and ude:	
	a)	detailed baseline data;	Section 6
	b)	a description of:	
		 the relevant statutory requirements (including any relevant approval, licence or lease conditions); 	Section 3
		any relevant limits or performance measures/criteria;	Section 5
		 the specific performance indicators that are proposed to be used to judge the performance of, or guide the implementation of, the project or any management measures; 	Section 5
	c)	a description of the measures that would be implemented to comply with the relevant statutory requirements, limits, or performance measures/criteria;	Sections 5, 7, 8 and 9
	d)	a program to monitor and report on the:	Sections 7, 8 and 11
		 impacts and environmental performance of the project; 	
		 effectiveness of any management measures (see c above); 	
	e)	a contingency plan to manage any unpredicted impacts and their consequences;	Section 9
	f)	a program to investigate and implement ways to improve the environmental performance of the project over time;	Sections 7 and 11
	g)	a protocol for managing and reporting any;	
		• incidents;	Section 12
		• complaints;	Section 13
		non-compliances with statutory requirements; and	Section 14
		 exceedances of the impact assessment criteria and/or performance criteria; and 	Section 9
	h)	a protocol for periodic review of the plan.	Sections 2 and 11
Со	nditi	on 7, Schedule 3	
7.	cor	addition to the standard requirements for management plans (see dition 2 of schedule 7), the Proponent shall ensure that the management as required under condition 6(f) above include:	
	a)	a program to collect sufficient baseline data for future Extraction Plans;	Section 10
	b)	a revised assessment of the potential environmental consequences of the Extraction Plan, incorporating any relevant information that has been obtained since this approval;	Section 4
	c)	a detailed description of the measures that would be implemented to remediate predicted impacts; and	Section 8
	d)	a contingency plan that expressly provides for adaptive management.	Section 9

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B		Page 7		
Document ID: Land Management Plan				

3.2 LICENCES, PERMITS AND LEASES

In addition to the Project Approval, all activities at or in association with the Metropolitan Coal Mine will be undertaken in accordance with the following licences, permits and leases which have been issued or are pending issue:

- The conditions of mining leases issued by the NSW Division of Resources and Geoscience (DRG), under the NSW *Mining Act*, 1992 (e.g. Consolidated Coal Lease [CCL] 703, Mining Lease [ML] 1610, ML 1702, Coal Lease [CL] 379 and Mining Purpose Lease [MPL] 320).
- The Metropolitan Coal Mining Operations Plan 1 October 2012 to 30 September 2019 approved by the DRG.
- The conditions of Environment Protection Licence (EPL) No. 767 issued by the NSW Environment Protection Authority (EPA) under the NSW Protection of the Environment Operations Act, 1997. Revision of the EPL will be required prior to the commencement of Metropolitan Coal activities that differ from those currently licensed.
- The prescribed conditions of specific surface access leases within CCL 703 for the installation of surface facilities as required.
- Water Access Licences (WALs) issued by the NSW Department of Primary Industries Water (now the Department of Industry – Water) under the NSW Water Management Act, 2000, including WAL 36475 under the Water Sharing Plan for the Greater Metropolitan Region Groundwater Sources 2011 and WAL 25410 under the Water Sharing Plan for the Greater Metropolitan Region Unregulated River Water Sources 2011.
- Mining and workplace health and safety related approvals granted by the NSW Resources Regulator and WorkCover NSW.
- Supplementary approvals obtained from WaterNSW for surface activities within the Woronora Special Area (e.g. fire road maintenance activities).

3.3 OTHER LEGISLATION

Metropolitan Coal will conduct the Project consistent with the Project Approval and any other legislation that is applicable to an approved Part 3A Project under the EP&A Act.

The following Acts may be applicable to the conduct of the Project (Helensburgh Coal Pty Ltd [HCPL], 2008)²:

- Biodiversity Conservation Act, 2016;
- Biosecurity Act, 2015;
- Contaminated Land Management Act, 1997;
- Crown Land Management Act, 2016;
- Dams Safety Act, 2015;
- Dangerous Goods (Road and Rail Transport) Act, 2008;
- Energy and Utilities Administration Act, 1987;
- Fisheries Management Act, 1994;
- Mining Act, 1992;

_

The list of potentially applicable Acts has been updated to reflect changes to the Acts that were in force at the time of submission of the Metropolitan Coal Project Environmental Assessment (Project EA) (HCPL, 2008).

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B		Page 8		
Document ID: Land Management Plan				

- Protection of the Environment Operations Act, 1997;
- Rail Safety (Adoption of National Law) Act, 2012;
- Roads Act, 1993;
- Water Act, 1912;
- Water Management Act, 2000;
- Water NSW Act, 2014;
- Work Health and Safety Act, 2011; and
- Work Health and Safety (Mines and Petroleum Sites) Act, 2013.

Relevant licences or approvals required under these Acts will be obtained as required.

4 REVISED ASSESSMENT OF POTENTIAL ENVIRONMENTAL CONSEQUENCES

4.1 LONGWALL 304 EXTRACTION LAYOUT

Longwall 304 and the area of land within 600 metres (m) of Longwall 304 secondary extraction are shown on Figures 1, 2 and 4. Longwall extraction will occur from north to south over a proposed void length of 1,286 m. The Longwall 304 layout includes a 163 m panel width (void) with 45 m pillar widths (solid).

Longwall 304 is scheduled to commence in July 2019 and be completed in December 2019.


The total cumulative predicted subsidence effects, subsidence impacts and/or environmental consequences at the completion of the Project are considered in the Metropolitan Coal Project Environmental Assessment (Project EA) (HCPL, 2008) and the Preferred Project Report (HCPL, 2009), and the cumulative subsidence effects, subsidence impacts and environmental consequences will be assessed in future Extraction Plans.

4.2 RELEVANT INFORMATION OBTAINED SINCE PROJECT APPROVAL

Visual inspections of cliffs and overhangs were conducted monthly when mining of Longwalls 20-22 and/or Longwalls 23-27 was within 400 m of sites COH1, COH2, COH3, COH4, COH5, COH6, COH6A, COH7, COH8, COH9, COH10, COH14, COH15 and COH16 (Figure 2) and following the completion of each longwall to record evidence of subsidence impacts. A vertical tension crack (approximately 50 millimetres [mm] wide and 15 m long) on the cliff face and a small rock fall (approximately 1.5 m long, 0.5 m wide and 0.5 m³) were recorded at site COH2 (Figure 2) in December 2013 during the mining of Longwall 22 (Metropolitan Coal, 2014). No additional subsidence impacts at the abovementioned cliff or overhang sites were recorded following the completion of Longwall 27 (Metropolitan Coal, 2017).

A new cliff and overhang site (COH17) was identified below the full supply level on the Eastern Tributary arm of the Woronora Reservoir in August 2018. Detailed baseline recording for this site has been conducted and is included in Appendix 1.

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B		Page 9		
Document ID: Land Management Plan				



Observations of steep slopes and land in general have been conducted by Metropolitan Coal and its contractors as part of routine works conducted in the catchment. In February 2012 during the mining of Longwall 21, a surface tension crack was recorded on Fire Trail 9C adjacent to Longwall 20, approximately 10 m long with a maximum width of 20 mm (Metropolitan Coal, 2011). In February 2017 a surface tension crack was recorded on a rock platform located over Longwall 25 in the vicinity of Aboriginal heritage site FRC 301 approximately 10 mm wide and 25 m long (Metropolitan Coal, 2017).

In September 2011 during the mining of Longwall 21, a rock ledge was recorded to have collapsed on the Unnamed Tributary/Tributary D, located to the south of Longwalls 20-22 (Metropolitan Coal, 2012). In July 2015 during the mining of Longwall 24, a rock ledge collapse was recorded on Tributary B (Metropolitan Coal, 2016a). In February 2017 rock fall from the underside of a sandstone boulder overhang, approximately 60 cm wide and 80 cm in length, was recorded in the vicinity of Aboriginal heritage site FRC 285 located over Longwall 22B (Metropolitan Coal, 2017).

The potential for impacts on public safety, as well as the potential environmental consequences of the observed subsidence impacts were assessed. None of the recorded subsidence impacts were considered to represent a safety or environmental hazard and no management measures were considered necessary.

The recorded subsidence impacts are consistent with the potential subsidence impacts described in the Project EA and Preferred Project Report.

4.3 ENVIRONMENTAL RISK ASSESSMENT

An Environmental Risk Assessment (ERA) was conducted for four of the key component plans of the Metropolitan Coal Longwall 304 Extraction Plan³ *viz.* Water Management Plan, Biodiversity Management Plan, Heritage Management Plan and this LMP to give appropriate consideration to risk assessment and risk management in accordance with the DP&E and DRE (2015) *Guidelines for the Preparation of Extraction Plans*.

The suitably qualified and experienced experts endorsed by the Secretary of the DP&E for the preparation of the Metropolitan Coal Longwall 304 Extraction Plan participated in the ERA⁴. The ERA process involved the key steps described below.

Review of Relevant Documentation

In preparation for the ERA workshop, the ERA participants reviewed a number of documents relevant to the risk assessment. This included (but was not limited to):

The Environmental Risk Analysis (SP Solutions, 2008) conducted for the Project EA (Appendix O of the Project EA).

Participants included Mr Peter DeBono (Mine Subsidence Engineering Consultants, Subsidence and Land), Dr Noel Merrick (HydroSimulations, Groundwater), Mr Lindsay Gilbert and Mr Tony Marszalek (Hydro Engineering & Consulting, Surface Water), Associate Professor Barry Noller (The University of Queensland, Surface Water Quality), Dr David Goldney (Cenwest Environmental Services, Fauna), Ms Elizabeth Norris (Ecoplanning, Flora), Mr Jamie Reeves (Niche Environment and Heritage, Heritage), Ms Stacey Gromadzki (Resource Strategies), Mr Jon Degotardi (Metropolitan Coal) and Mr Stephen Love (Metropolitan Coal).

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B		Page 11		
Document ID: Land Management Plan				

Individual risk assessments have been undertaken separately for the Metropolitan Coal Longwall 304 Built Features Management Plan and the Metropolitan Coal Longwall 304 Public Safety Management Plan, and are reported in their respective documents.

- The Preferred Project Report (HCPL, 2009). During the NSW Government's assessment phase of the Project EA, and in recognition of concerns raised by key stakeholders during the formal Planning Assessment Commission (PAC) assessment process, HCPL considered it appropriate to reduce the proposed extent of the original Project longwall mining area (i.e. Longwalls 20-44). This reduction in the extent of longwall mining resulted in a significant reduction to the extent of potential subsidence effects to the Waratah Rivulet and the Eastern Tributary and a reduction in the consequential potential environmental impacts.
- The Longwalls 301-303 Environmental Risk Assessment Report (Metropolitan Coal, 2016)⁵.
- Subsidence predictions and assessments included in Metropolitan Coal's Longwalls 304-306 First Workings Application (correspondence to the DP&E dated 9 October 2018).
- Information regarding the Longwalls 301-303 layout and requirement to have no further exceedance of the relevant performance measure applicable to the Eastern Tributary.
- Subsidence predictions for the proposed Longwall 304 Extraction Plan layout (including subsidence contours, Eastern Tributary, cliff sites, upland swamps and Aboriginal heritage sites).

Risk Identification

The participants were asked to identify any additional (specific) issues/risks and/or changes to previously assessed levels of risk in preparation for the ERA workshop.

ERA Workshop

The ERA workshop for Longwall 304 was conducted on 23 November 2018, with some participants attending via video conferencing and others attending in person at the Metropolitan Coal Mine. The ERA workshop was facilitated by an independent specialist, Operational Risk Mentoring.

The general consensus of the workshop participants was the additional (specific) issues/risks identified for Longwall 304 were broadly assessed and ranked as part of the 2008 Environmental Risk Analysis and Longwalls 301-303 ERA. It was considered that the five "loss scenarios" identified for the Longwalls 301-303 ERA (within two key topics of discussion viz. Upland Swamps and the Eastern Tributary) were appropriate for the assessment of Longwall 304.

The assessed level of risk for each of the five loss scenarios identified for Longwalls 301-303 were reviewed for Longwall 304, considering the experience to date and using the same probability, consequence and risk rankings tables. A key assumption that was applied to the Longwall 304 ERA was that the Longwall 304 Extraction Plan layout would not result in any further exceedance of the performance measure relevant to the Eastern Tributary.

The assessed levels of risk for Longwalls 301-303 were considered by the participants to remain valid for Longwall 304. The re-assessed risk rankings for Longwall 304 were within the "low" range and consequently the potential outcomes can still be integrated into the existing management systems for effective review and monitoring (Operational Risk Mentoring, 2019).

This report includes a description of the approved changes made to the first workings layout for Longwalls 301-303 in 2015 and 2016.

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 12						
Document ID: Land Management Plan	Document ID: Land Management Plan					

Review of Issues/Risks and Assessed Levels of Risk for Revised Longwall 304 Extraction Plan Layout

Subsequent to the Longwall 304 ERA workshop, Metropolitan Coal proposed a change to the layout of Longwalls 303 and 304 for the Longwall 304 Extraction Plan. The participants were asked to review a number of additional documents relevant to the risk assessment and revised layouts and Longwall 304 risk assessment. This included:

- Metropolitan Coal's Longwall 303 Extension Application (February 2019), which seeks further approval from the Secretary to undertake secondary extraction beyond 1,143 m in Longwall 303 for the first 1,325 m of Longwall 303. This application includes details of Metropolitan Coal's proposed monitoring and adaptive management approach for the Eastern Tributary. The application states that the same monitoring and adaptive management approach for the Eastern Tributary will be applied to Longwall 304.
- Confirmation that the Longwall 304 Extraction Plan will be based on a Longwall 303 extraction length of 1,325 m and a Longwall 304 extraction length of 1,286 m, noting that this layout differs from that assessed in the ERA Workshop (November 2018), with Longwall 303 being extended by 128 m and Longwall 304 being shortened by 42 m.
- A figure showing the revised Longwall 303 and Longwall 304 layouts to be used for the Longwall 304 Extraction Plan compared to the longwall lengths assessed by the ERA workshop.
- The MSEC (2019) Metropolitan Mine Longwall 304 Subsidence Predictions and impact Assessments for the Natural and Built Features in Support of the Extraction Plan report (Report MSEC1009), detailing the subsidence predictions and impact assessments for the revised longwall layout for the Longwall 304 Extraction Plan.

The ERA participants were asked to identify any additional (specific) issues/risks and/or changes to previously assessed levels of risk associated with the revised Longwall 304 Extraction Plan Layout. The assessed levels of risk were considered to remain valid for the revised Longwall 304 Extraction Plan layout.

ERA Report Review

All ERA participants were asked to review the draft report that was prepared to summarise the outcomes of the risk assessment workshop and risk review as a result of the change in longwall layout. Participants' comments were incorporated into the final Operational Risk Mentoring (2019) report.

This LMP has been prepared to provide for effective management of the identified subsidence risks.

4.4 CLIFFS AND OVERHANGS

Consistent with the Project Approval, cliffs are defined as a continuous rock face, including overhangs, having a minimum height of 10 m and a slope of greater than 66 degrees (°). The location of cliffs within the Project underground mining area (Figure 2) was determined by MSEC (2008) from site inspections and from 1 m surface contours of the area. Overhangs associated with cliffs and/or considered sensitive to potential mine subsidence movements (due to their location relative to the Waratah Rivulet) were also identified within the Project underground mining area (Figure 2).

One cliff and overhang site (COH17) has recently (August 2018) been identified within the Longwall 304 35° angle of draw and/or predicted 20 mm subsidence contour (Figure 4).

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B		Page 13		
Document ID: Land Management Plan				

4.4.1 Revised Subsidence Predictions

The subsidence predictions for Longwall 304 in relation to cliff sites within the 35° and/or predicted 20 mm subsidence contour (i.e. COH17) have been prepared by MSEC (2019). Table 2 compares the predicted subsidence parameter for the Longwall 304 Extraction Plan with those for the Preferred Project Layout (at the completion of Longwall 304).

The maximum predicted vertical subsidence, tilt and curvature for COH17 based on the Extraction Plan Layout are less than the maxima predicted based on the Preferred Project Layout (Table 2).

The next nearest cliffs are located more than 600 m to the west of Longwall 304 (Figure 4). At these distances, the cliffs are not expected to experience any measurable vertical subsidence resulting from the extraction of Longwall 304. The predicted valley related movements in these locations resulting from these longwalls are less than 20 mm upsidence and less than 20 mm closure. The strains due to these valley related effects are not expected to be measurable.

Table 2
Revised Subsidence Predictions for Cliffs and Overhangs

	Maximum Predicted Conventional Subsidence for Cliff COH17				
Longwall	Subsidence ¹ (mm)	Tilt² (mm/m)	Hogging Curvature ³ (km ⁻¹)	Sagging Curvature ³ (km ⁻¹)	
Preferred Project Layout4	350	2.5	0.01	0.03	
Longwall 304 Extraction Plan Layout ⁵	40	< 0.5	< 0.01	< 0.01	

Source: after MSEC (2019).

- ⁴ After completion of Longwall 304 of the Preferred Project Layout.
- ⁵ After completion of Longwall 304 of the Extraction Plan Layout.

mm = millimetres

mm/m= millimetres per metre

km⁻¹ =1/kilometres

4.4.2 Revised Assessment of Potential Subsidence Impacts and Environmental Consequences

As described in Section 4.4.1, the maximum predicted vertical subsidence, tilt and curvatures for cliff COH17, based on the Extraction Plan Layout, are less than the maxima predicted based on the Preferred Project Layout.

Cliff COH17 is located outside, and 280 m from, the extent of Longwall 304 and the cliff is predicted to experience low magnitudes of subsidence, and tilt and curvatures less than typical survey accuracy. Although isolated rock falls have been observed over solid coal outside the extracted goaf areas of longwall mining in the Southern Coalfield, there have been no recorded cliff instabilities outside the extracted goaf areas of longwall mining in the Southern Coalfield. It is possible that isolated rock falls could occur as a result of the extraction of Longwall 304. It is not expected, however, that any large cliff instabilities would occur as a result of the extraction of Longwall 304, as the longwall is not proposed to be extracted directly beneath the cliff and overhangs (MSEC, 2019).

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B		Page 14	
Document ID: Land Management Plan			

Subsidence refers to vertical displacements of the ground.

² Tilt is the change in the slope of the ground as a result of differential subsidence, and is calculated as the change in subsidence between two points divided by the distance between those points.

³ Curvature is the second derivative of subsidence, the rate of change of tilt, and is calculated as the change in tilt between two adjacent sections of the tilt profile divided by average length of those sections.

As described above, the next nearest cliffs are located approximately 600 m to the west of Longwall 304 (Figure 4). At this distance, it is unlikely that the cliffs would experience adverse impacts resulting from the extraction of Longwall 304 (MSEC, 2019).

4.5 STEEP SLOPES

Consistent with the Project Approval, steep slopes are defined as an area of land having a natural gradient of between 33° and 66°. In the Project EA subsidence assessment (Appendix A of the Project EA) MSEC (2008) defined steep slopes as an area of land having a natural gradient of between 18° and 63°. The steep slopes were identified from surface level contours generated from 1 m contours of the area. Both definitions of steep slopes are shown on Figures 2 and 4.

Steep slopes have been identified to highlight areas where existing ground slopes may be marginally stable. However, no significant slope failures have been observed in the Southern Coalfield as a result of longwall mining. Steep slopes within 600 m of Longwall 304 secondary extraction are shown on Figure 4.

The surface soils generally consist of soils derived from Hawkesbury Sandstone, in varying stages of weathering and fracturing. The majority of the slopes are stabilised, to some extent, by trees and other natural vegetation.

4.5.1 Revised Subsidence Predictions

A summary of the maximum predicted values of incremental conventional subsidence, tilt and curvature due to Longwall 304 extraction is provided in Table 3.

Table 3

Maximum Predicted Incremental Conventional Subsidence, Tilt and Curvature
Resulting from Longwall 304 Extraction

	Maximum Predicted Incremental Conventional			
Longwall	Subsidence ¹ (mm)	Tilt² (mm/m)	Hogging Curvature ³ (km ⁻¹)	Sagging Curvature ³ (km ⁻¹)
Due to LW304	625	4	0.04	0.06

Source: after MSEC (2019).

mm = millimetres

mm/m= millimetres per metre

km⁻¹ =1/kilometres

A comparison of the maximum predicted total subsidence parameters resulting from the extraction of Longwall 304 (i.e. the Extraction Plan Layout), with those based on the Preferred Project Layout for Longwall 304, are provided in Table 4. The values are the maxima anywhere within the Longwall 304 35° angle of draw and/or predicted 20 mm subsidence contour (Figure 4) (MSEC, 2019).

The maximum predicted total subsidence, tilt and sagging curvature based on the Extraction Plan Layout for Longwall 304 are slightly less than the maxima based on the Preferred Project Layout for Longwall 304 (Table 4). The maximum predicted total hogging curvature is the same for both layouts (MSEC, 2019).

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B Page 15				
Document ID: Land Management Plan				

¹ Subsidence refers to vertical displacements of the ground.

² Tilt is the change in the slope of the ground as a result of differential subsidence, and is calculated as the change in subsidence between two points divided by the distance between those points.

³ Curvature is the second derivative of subsidence, the rate of change of tilt, and is calculated as the change in tilt between two adjacent sections of the tilt profile divided by average length of those sections.

Table 4

Comparison of Maximum Predicted Total Conventional Subsidence Parameters based on the
Preferred Project Layout and the Extraction Plan Layout

Layout	Maximum Predicted Total Conventional			
	Subsidence (mm)	Tilt (mm/m)	Hogging Curvature (km ⁻¹)	Sagging Curvature (km ⁻¹)
Preferred Project Layout (LW304)	1150	5.5	0.05	0.14
Extraction Plan Layout	1050	5.0	0.05	0.13

Source: after MSEC (2019).

mm = millimetres

mm/m= millimetres per metre

km⁻¹ =1/kilometres

4.5.2 Revised Assessment of Potential Subsidence Impacts and Environmental Consequences

The steep slopes could experience the full range of predicted subsidence movements, as summarised in Table 3 and Table 4. The maximum predicted subsidence parameters for the steep slopes, based on the Extraction Plan Layout, are similar to the maxima based on the Preferred Project Layout, as summarised in Table 4 (MSEC, 2019).

The potential impacts on steep slopes, based on the Extraction Plan Layout, are the same as those assessed based on the Preferred Project Layout, as described in the Project EA and Preferred Project Report, specifically, the potential for ground surface cracking. The size and extent of surface cracking at the steep slopes is expected to be similar to that observed during the extraction of earlier longwalls at Metropolitan Coal (MSEC, 2019).

Potential environmental consequences of surface cracking, such as the formation of areas capable of trapping some ground dwelling fauna and impacts on Aboriginal heritage sites, are the subject of other Metropolitan Coal management plans such as the Metropolitan Coal Longwall 304 Biodiversity Management Plan and Metropolitan Coal Longwall 304 Heritage Management Plan (Figure 3). A protocol is outlined in Sections 8 and 9 that ensures the potential environmental consequences of recorded subsidence impacts are assessed as a component of the LMP monitoring program and that this LMP initiates and links actions with other plans where appropriate.

Another potential consequence of surface cracking is the potential for impacts on public safety. Public safety will be addressed in the Metropolitan Coal Longwall 304 Public Safety Management Plan (Figure 3).

4.6 LAND IN GENERAL

Land in general refers to the general landscape other than cliffs and steep slopes. There are rock ledges, also called rock outcrops and minor cliffs, which occur within 600 m of Longwall 304 (MSEC, 2019).

Land in general includes other land features such as fire trails and vehicular tracks, however excludes surface features such as streams and upland swamps which are addressed in other Metropolitan Coal management plans and programs. Unsealed vehicular tracks and fire trails are located throughout the Project underground mining area and above Longwall 304 (Figure 4).

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 1						
Document ID: Land Management Plan						

4.6.1 Revised Subsidence Predictions

Land in general could experience the full range of predicted subsidence movements, as summarised in Table 3 and Table 4. The maximum predicted subsidence parameters for land in general, based on the Extraction Plan Layout, are similar to the maxima based on the Preferred Project Layout, as summarised in Table 4 (MSEC, 2019).

4.6.2 Revised Assessment of Potential Subsidence Impacts and Environmental Consequences

As described in Section 4.6.1, land in general could experience the full range of predicted subsidence movements, as summarised in Table 3 and Table 4.

The potential impacts on land in general, based on the Extraction Plan Layout, are the same as those assessed based on the Preferred Project Layout, as described in the Project EA and Preferred Project Report, specifically, the fracturing of sandstone (including surface tension cracking) and subsequent rock falls (particularly where rock ledges are marginally stable).

Fire trails and vehicular tracks could experience surface cracking during the mining period, particularly where the trails/tracks are located near the tops of existing slopes or at the bottom of valleys.

In relation to potential environmental consequences, the aesthetics of the landscape could be altered by rock falls, while surface cracking has the potential to form areas capable of trapping some ground dwelling fauna. Rock falls and/or surface cracking also have potential to impact surface water quality and Aboriginal heritage sites. A protocol is outlined in Sections 8 and 9 that ensures the potential environmental consequences of recorded subsidence impacts are assessed as a component of the LMP monitoring program and that this LMP initiates and links actions with other plans where appropriate.

Another potential consequence of rock falls and surface cracking is the potential for impacts on public safety. Public safety is addressed in the Metropolitan Coal Longwall 304 Public Safety Management Plan (Figure 3).

5 PERFORMANCE MEASURES AND INDICATORS

5.1 CLIFFS AND OVERHANGS

The Project Approval requires Metropolitan Coal not to exceed the subsidence impact performance measures outlined in Table 1 of Condition 1, Schedule 3. The subsidence impact performance measure specified in Table 1 of Condition 1, Schedule 3 in relation to land is:

Less than 3% of the total length of cliffs (and associated overhangs) within the mining area experience mining-induced rock fall.

This performance measure is based on the results of the Project EA subsidence assessment (MSEC, 2008). Most of the mining-induced cliff falls have been observed where the depth of cover to mining was shallow, as in the Western Coalfield, and few cliff falls or rock falls have been observed where the depth of cover is more than 400 m, as is generally the case in the Southern Coalfield (MSEC, 2008). Based on comparisons against other mines where cliff lines have been undermined in the Southern Coalfield, the length of potential cliff instabilities are expected to be less than 3% of the lengths of these cliffs.

Metropolitan Coal – Land Management Plan							
Revision No. LMP-R01-B Page 17							
Document ID: Land Management Plan	Document ID: Land Management Plan						

Minor rock falls have been observed to occur naturally at locations where there has been no mining and this is a reminder that cliffs and rock overhangs are landforms that are part of a naturally occurring erosion/weathering cycle and they are often only marginally stable (*ibid*.). This highlights that caution is required when inspecting the surface near these natural features and when proposing any surface management plans near or around cliffs and overhangs during and immediately after mining (MSEC, 2008).

Consistent with the Project EA subsidence assessment (MSEC, 2008), cliff instabilities (cliffs within the mining area that experience mining-induced rock fall) are considered to result in freshly exposed surfaces dissimilar to natural weathering processes. They are represented by the exposure of a fresh face of rock and debris scattered around the base of the cliff or overhang.

Metropolitan Coal will assess the Project against the following performance indicator:

Cliff site COH17 experiences cliff instabilities that do not require management measures to be implemented.

Section 7 describes the monitoring and TARP that will be used to assess the Project against this performance indicator.

Table 5 shows the length of cliffs and associated overhangs within the Project underground mining area. Figure 2 shows the location of the cliffs and associated overhangs in the Project underground mining area. Table 5 indicates the total length of cliffs and associated overhangs identified within the Project underground mining area is approximately 827 m.

Table 5
Length of Cliffs and Overhangs within the Project Underground Mining Area

Site	Approximate Overall Length (m)		
COH1	143		
COH2	95		
COH3	55		
COH4	19		
COH5	35		
COH6	35		
COH6A	10		
COH7	50		
COH8	40		
COH9	30		
COH10	50		
COH11	20		
COH12	30		
COH13	40		
COH14	45		
COH15	20		
COH16	30		
COH17	80		
Total Length	827		

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page						
Document ID: Land Management Plan						

A Land Management Plan – Subsidence Impact Register has been used to progressively monitor the total length of cliffs and associated overhangs that experience cliff instabilities. Following the completion of Longwall 27 and prior to the commencement of Longwall 301, one cliff site (COH2) located over Longwall 20 has been recorded with cliff instabilities, approximately 1.5 m in length (Appendix 2).

One cliff and overhang site (COH17) has been identified within the Longwall 304 35° angle of draw and/or predicted 20 mm subsidence contour (Figure 4). Detailed baseline recording for this site has been conducted and is included in Appendix 1.

The next nearest cliff and overhang sites are located more than 600 m to the west of Longwall 304. At these distances, the cliff and overhang sites are not expected to experience any measurable vertical subsidence resulting from the extraction of Longwall 304.

5.2 STEEP SLOPES AND LAND IN GENERAL

The potential for the fracturing of sandstone (including surface tension cracking) and subsequent rock falls (particularly where rock ledges are marginally stable) has been identified, similar to that observed during the extraction of previous longwalls at Metropolitan Coal.

Metropolitan Coal will assess the Project against the following performance indicator:

Steep slopes and land in general do not experience sandstone fracturing/cracking or rock falls that require management measures to be implemented.

Section 7 describes the monitoring and TARP that will be used to assess the Project against this performance indicator.

6 BASELINE DATA

6.1 CLIFFS AND OVERHANGS

As described in Section 4.4, cliffs are defined as a continuous rock face, including overhangs, having a minimum height of 10 m and a slope of greater than 66 degrees (°). The location of cliffs within the Project underground mining area (Figure 2) was determined by MSEC (2008) from site inspections and from 1 m surface contours of the area.

Overhangs associated with cliffs and/or considered sensitive to potential mine subsidence movements (due to their location relative to the Waratah Rivulet) were also identified within the Project underground mining area (Figure 2).

Site inspections of cliffs and overhangs within 600 m of Longwalls 20-27 secondary extraction were conducted by MSEC prior to the commencement of Longwalls 20-22 and/or Longwalls 23-27. A site inspection of cliff and overhang site COH17 was conducted by MSEC prior to the commencement of Longwall 303. The baseline characteristics of each cliff and overhang were recorded. The data obtained includes:

- · photographic records of each cliff and overhang;
- sketches of overhangs;

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 1						
Document ID: Land Management Plan						

- mapping of the approximate location of the cliff/overhang face and the rear extent of the overhang/undercut; and
- mapping of the location of the cliff or overhang relative to the Waratah Rivulet (where relevant).

The detailed baseline information for each site containing a cliff and/or overhangs is provided in Appendix 1, namely sites COH1, COH2, COH3, COH4, COH5, COH6, COH6A, COH7, COH8, COH9, COH10, COH14, COH15, COH16 and COH17.

The extent of weathering was observed to vary from well weathered rock faces to relatively freshly exposed rock surfaces where weathering was not advanced and vegetation cover had not established.

Jointing is considered ubiquitous within the Hawkesbury Sandstone and cliff lines have developed in association with the conjugate joint sets present. Differential weathering has exposed the sub-horizontal layers at varying rates, reflecting the natural variation in rock strength through the profile. In places the differential weathering has resulted in overhangs, essentially reflecting the erosion of weaker layers below more competent strata units that can span varying distances.

Table 5 in Section 5.1 shows the length of cliffs and associated overhangs within the Project underground mining area.

6.2 STEEP SLOPES AND LAND IN GENERAL

A series of en-echelon rock ledges occur on the steep slopes and other land, as well as other rock formations such as boulders and rock pavements. Natural cracks along exposed rock ledges are common and migration of leaf litter and establishment of vegetation within these zones is common. Freshly exposed cracks attributable to mining would be readily apparent, at least in areas of no soil cover

No surface tension cracks as a result of previous mining had been observed within the 35° angle of draw and/or predicted 20 mm subsidence contour of Longwall 304 at the time of LMP preparation.

7 MONITORING

The monitoring program described in Sections 7.1 and 7.2 will be conducted during the mining of Longwall 304.

The TARP that will be used to assess the environmental performance of the Project is provided in Section 7.3.

7.1 SUBSIDENCE PARAMETERS

Subsidence parameters will be measured in accordance with the Metropolitan Coal Longwall 304 Subsidence Monitoring Program (Figure 3).

In summary, surveys will be conducted to measure subsidence movements in three dimensions using a total station survey instrument. Subsidence movements will be measured along subsidence lines that have been positioned across the general landscape.

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 20						
Document ID: Land Management Plan						

7.2 SUBSIDENCE IMPACTS

7.2.1 Cliffs and Overhangs

Following the completion of Longwall 27 extraction, cliff sites COH1, COH2, COH3, COH4, COH5, COH6, COH6A, COH7, COH8, COH9, COH10, COH14, COH15 and COH16 were inspected to record any additional subsidence impacts (e.g. cliff instabilities and cracking) to those previously recorded. The visual inspections did not record any additional subsidence impacts.

Visual inspections for subsidence impacts on cliff site COH17 will be conducted monthly when Longwall 303 extraction is within 400 m of the site and at the completion of Longwall 303. Visual inspections for subsidence impacts will also be conducted monthly when Longwall 304 is within 400 m of the site and at the completion of Longwall 304. Additional visual observations of subsidence impacts will be conducted during routine works and sampling by Metropolitan Coal and its contractors.

In the event subsidence impacts are identified on cliff and overhang site COH17, the following details will be noted and/or photographed:

- the date of the inspection;
- the location of longwall extraction (i.e. the longwall chainage);
- the location of the cliff instability (i.e. freshly exposed rock face and debris scattered around the base of the cliff or overhang) relative to the cliff face or overhang;
- the nature and extent of the cliff instability (including an estimate of volume);
- the length of the cliff instability;
- other relevant aspects such as water seepage (which can indicate weaknesses in the rock);
- whether any actions are required (for example, implementation of appropriate safety controls, review of public safety etc.); and
- any other relevant information.

The information obtained will be recorded in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact Register Assessment Form (Appendix 2) and reported in accordance with the Project Approval conditions.

The information obtained will be used to assess the potential environmental consequences of the subsidence impact. Specific details that will be noted and/or photographed to assess the potential environmental consequences of the subsidence impact include:

- the nature and extent of impacts on the aesthetic values of the land feature;
- any areas of erosion or sedimentation arising from mining activities;
- the co-ordinates of the subsidence impact to assess impacts on known Aboriginal heritage sites;
- nature and extent of impacts on potential flora and fauna habitats;
- evidence of impacts on terrestrial fauna (e.g. observed fauna mortality); and
- any impacts on the serviceability of fire trails/vehicular tracks and/or stream crossings.

Metropolitan Coal will document the assessment of potential environmental consequences in the Land Management Plan – Subsidence Impact Register Assessment Form (Appendix 2).

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 2						
Document ID: Land Management Plan						

The information recorded will be used to assess the Project against the following performance indicator in accordance with the TARP (Section 7.3):

Cliff site COH17 experiences cliff instabilities that do not require management measures to be implemented.

The information recorded will also be used to assess the Project against the following performance measure in accordance with the TARP (Section 7.3):

Less than 3% of the total length of cliffs (and associated overhangs) within the mining area experience mining-induced rock fall.

7.2.2 Steep Slopes and Land in General

Visual inspections for subsidence impacts on steep slopes and land in general within 600 m of Longwalls 20-27 and Longwalls 301-304 extraction will be conducted by Metropolitan Coal and its contractors during catchment visits, sampling and routine works conducted in the catchment.

In the event subsidence impacts are identified within 600 m of Longwalls 20-27 or Longwalls 301-303 (that were not previously recorded during the mining of Longwalls 20-27 or Longwalls 301-303), or within 600 m of Longwall 304, the following details will be noted and/or photographed:

- the location, approximate dimensions (length, width and depth), and orientation of surface tension cracks:
- the location of the surface tension crack in relation to fire trails or vehicular tracks;
- the location and approximate dimensions of rock falls (e.g. rock ledges);
- whether any actions are required (for example, implementation of appropriate safety controls, review of public safety etc.); and
- any other relevant information.

The date of the observation, details of the observer and the location of longwall extraction will also be documented.

The information obtained will be recorded in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact Register Assessment Form (Appendix 2) and reported in accordance with the Project Approval conditions.

The information obtained will be used to assess the potential environmental consequences of the subsidence impact. Specific details that will be noted and/or photographed to assess the potential environmental consequences of the subsidence impact include:

- the nature and extent of impacts on the aesthetic values of the land feature;
- any areas of erosion or sedimentation arising from mining activities;
- the co-ordinates of the subsidence impact to assess impacts on known Aboriginal heritage sites;
- nature and extent of impacts on potential flora and fauna habitats;
- evidence of impacts on terrestrial fauna (e.g. observed fauna mortality); and
- any impacts on the serviceability of fire trails/vehicular tracks and/or stream crossings.

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 22						
Document ID: Land Management Plan						

Metropolitan Coal will document the assessment of potential environmental consequences in the Land Management Plan – Subsidence Impact Register Assessment Form (Appendix 2).

The information recorded will be used to assess the Project against the following performance indicator in accordance with the TARP (Section 7.3):

Steep slopes and land in general do not experience sandstone fracturing/cracking or rock falls that require management measures to be implemented.

7.3 TRIGGER ACTION RESPONSE PLAN

The TARP for cliffs and overhangs, steep slopes and land in general is detailed in Table 6.

If monitoring indicates a performance indicator has been exceeded, management measures will be developed in consultation with the relevant landholder and DP&E (Section 8).

8 MANAGEMENT MEASURES

Potential management measures that will be considered to mitigate/remediate environmental consequences are provided in Tables 7 and 8. The implementation of management measures will be considered with regard to the specific circumstances of the subsidence impact (e.g. the location, nature and extent of the impact) and the assessment of environmental consequences. The implementation of management measures will be related to the scale of impact and the ability to, and value in, undertaking mitigation measures on a case by case basis. This means that management measures will be considered and may be implemented prior to the land performance measure being exceeded. Management measures will be implemented, as appropriate, to comply with the relevant statutory requirements and the subsidence impact performance measure.

Metropolitan Coal will assess the potential environmental consequences of the recorded subsidence impact on known Aboriginal heritage sites, and where appropriate, implement measures in accordance with the Metropolitan Coal Longwall 304 Heritage Management Plan.

In the event the subsidence impacts are deemed to present a safety hazard (i.e. regardless of the nature or extent of the subsidence impact), actions will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan.

Where significant subsidence impacts on fire trails or vehicular tracks are detected (e.g. those that affect the serviceability of the fire trails or vehicular tracks) or at any time Metropolitan Coal or the landholder considers that the integrity of the fire trails or vehicular tracks may be compromised, the following management measures will be implemented. Where significant cracks are detected, the cracks will be repaired as soon as practicable in consultation with the landholder. This may include the use of earthmoving equipment if considered the most appropriate means of repair. Appropriate sedimentation controls will be implemented during repair works.

The implementation of any stabilisation techniques or measures to improve the aesthetic value of the feature will be conducted in consultation with the landholder. Appropriate erosion and sediment control techniques will be implemented as required. As described in Table 8, the landholder will be consulted in the event Metropolitan Coal proposes to in-fill any surface tension cracks.

Follow-up inspections will be conducted to assess the effectiveness of implemented management measures and the requirement for any additional management measures. Management measures will be reported in the Annual Review (Section 11).

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B Page 2						
Document ID: Land Management Plan						

Table 6
Trigger Action Response Plan – Cliffs and Overhangs, Steep Slopes and Land in General

Performance Measure	Performance Indicator	Monitoring Sites	Parameters	Frequency/ Sample Size	Analysis Methodology	Error Types	Baseline		Significance Levels/Ti	riggers/Action/Response
Less than 3% of the total length of cliffs (and	Cliff site COH17 experiences cliff instabilities that do not require	Cliff site COH17	Cliff instabilities.	On a monthly basis when Longwall 304 extraction is	Visual inspection.	Assessment of mining versus natural causes.	 Photographic record of cliff and overhang site COH17 provided in Appendix 1. 	Level 1	No subsidence impacts (i.e. cliff instabilities) recorded at cliff site COH17.	Continue monitoring. Six monthly reporting.
associated overhangs) within the mining area experience mining-induced rock fall ¹	management measures to be implemented.		extraction is within 400 m of the site. • As part of routine works conducted in the catchment. • Following the completion of Longwall 304 extraction.		COH17 exhibits exposed surfaces of variable weathering. Natural fractur (joints) present.	surfaces of variable weathering. Natural fractures	Level 2	Subsidence impacts (i.e. cliff instabilities) recorded at cliff site COH17, however, do not require management measures to be implemented.	Record subsidence impacts in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact Register Assessment Form. Assess whether the impact is considered to be a safety hazard and the potential environmental consequences of the subsidence impact and document assessment in Land Management Plan – Subsidence Impact Register Assessment Form. Assess requirement for management measures. Six monthly reporting.	
								Level 3	Subsidence impacts (i.e. cliff instabilities) recorded at cliff site COH17, and require management measures to be implemented.	In the event the subsidence impacts are deemed to present a safety hazard (i.e. regardless of the nature or extent of the subsidence impact), actions will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan.
										Record subsidence impacts in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact Register Assessment Form.
										Assess the potential environmental consequences of the subsidence impact and document assessment in Land Management Plan – Subsidence Impact Register Assessment Form.
										Assess requirement for management measures.
										Consult with landholder and DP&E in relation to proposed management measures.

Visual inspections of the cliff and overhang sites COH1, COH2, COH3, COH4, COH5, COH6, COH6, COH6, COH7, COH8, COH10, COH

Metropolitan Coal – Land Management Plan						
Revision No. LMP-R01-B		Page 24				
Document ID: Land Management Plan						

Table 6 (Continued) Trigger Action Response Plan – Cliffs and Overhangs, Steep Slopes and Land in General

Performance Measure	Performance Indicator	Monitoring Sites	Parameters	Frequency/ Sample Size	Analysis Methodology	Error Types	Baseline		Significance Levels/Triggers/Action/Response																																						
-	Steep slopes and land in general experience sandstone fracturing/cracking and rock falls that do not require	Steep slopes and land in general within 600 m of Longwall (LW) 20-27 and LW301-304.	Sandstone fracturing/cracking and rock falls.	Visual inspections as part of routine works conducted in the catchment.	Visual inspection. The Land Management Plan – Subsidence Impact Register.	Assessment of mining versus natural causes.	 Some surface tension cracks on steep slopes and land in general within 600 m of LW20-27. No surface tension cracks recorded as a result of previous mining within 600 m 	Level 1	No subsidence impacts (i.e. sandstone fracturing/cracking and rock falls) recorded on steep slopes or land in general not previously recorded within 600 m of LW20-27 or LW301-304 (after LW304 commencement).	Continue monitoring. Six monthly reporting.																																					
	management measures to be implemented.	and Assessment Form will be used to monitor subsidence impacts and determine management and Of LW301-303 at the time LMP development. Two rock ledges (on stre have collapsed within 60 of LW20-27. Rock fall from the unders of a sandstone boulder	of LW301-303 at the time of LMP development. Two rock ledges (on streams) have collapsed within 600 m of LW20-27. Rock fall from the underside of a sandstone boulder overhang within 600 m of	Level 2	Subsidence impacts (i.e. sandstone fracturing/cracking and rock falls) on steep slopes or land in general recorded within 600 m of LW20-27 or LW301-304 (after LW304 commencement) additional to those previously recorded, however do not require management measures to be implemented.	In the event the subsidence impacts are deemed to present a safety hazard (i.e. regardless of the nature or extent of the subsidence impact), actions will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan. Record subsidence impacts in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact																																									
					requirements.		 LW20-27. No rock ledge collapses recorded as a result of mining of LW301-303 at the time of LMP development. No rock ledge collapses recorded as a result of 			Register Assessment Form. Assess the potential environmental consequences of the subsidence impact and document assessment in Land Management Plan – Subsidence Impact Register Assessment Form. Assess requirement for management measures. Six monthly reporting.																																					
																																											recorded as a result of previous mining within 600 m of LW304 at the time of LMP development.	of LW304 at the time of LMP	Level 3	Subsidence impacts (i.e. sandstone fracturing/cracking and rock falls) on steep slopes or land in general recorded within 600 m of LW20-27 or LW301-304 (after LW304 commencement) additional to those previously recorded and require management measures to be implemented.	In the event the subsidence impacts are deemed to present a safety hazard (i.e. regardless of the nature or extent of the subsidence impact), actions will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan. Record subsidence impacts in the Land Management Plan – Subsidence Impact Register and Land Management Plan – Subsidence Impact Register Assessment Form.
										Assess the potential environmental consequences of the subsidence impact and document assessment in Land Management Plan – Subsidence Impact Register Assessment Form.																																					
										Assess requirement for management measures. Consult with landholder and DP&E in relation to proposed management measures.																																					

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B		Page 25
Document ID: Land Management Plan		

Table 7 Potential Management Measures – Cliffs and Overhangs

Environmental	Potential Management Measures		
Consequence	Measure	Description	
Impacts on aesthetic values	Stabilisation techniques	Installation of artificial rock support (e.g. rock bolts, cable bolts).	
		Installation of standing supports (e.g. timber props, sandbags).	
		Scaling/dislodgement/removal of remaining loose rock.	
	Improvement of appearance	Application (i.e. spraying) of product to enhance the weathered appearance of the cliff face (e.g. milk to enhance bacterial activity and darkening of exposed rock appearance).	
		Planting of endemic native vegetation at the base of the cliff face/overhang.	
Impacts on surface	Stabilisation	Installation of artificial rock support (e.g. rock bolts, cable bolts).	
water quality	techniques	Installation of standing supports (e.g. timber props, sandbags).	
		Scaling/dislodgement/removal of remaining loose rock.	
	Erosion and	Implementation of erosion and sediment control measures, such as:	
	sediment control techniques	- Installation of sediment fences downslope of erosion areas.	
	teerinques	 Stabilisation of erosion areas using rock or other appropriate materials. 	
		 Other erosion and sediment control measures consistent with relevant guidelines. 	
Impacts on flora,	Stabilisation techniques	Installation of artificial rock support (e.g. rock bolts, cable bolts).	
fauna, and/or their habitats		Installation of standing supports (e.g. timber props, sandbags).	
		Scaling/dislodgement/removal of remaining loose rock.	
	Erosion and	Implementation of erosion and sediment control measures, such as:	
	sediment control techniques	- Installation of sediment fences downslope of erosion areas.	
	tosimiquos	 Stabilisation of erosion areas using rock or other appropriate materials. 	
		 Other erosion and sediment control measures consistent with relevant guidelines. 	
Aboriginal heritage Stabilisation techniques, salvage of artefacts		Aboriginal heritage management measures will be implemented in accordance with the Metropolitan Coal Longwall 304 Heritage Management Plan, such as:	
		 Establishing an artificial support between the roof and floor, known as standing supports. 	
		 Installation of an artificial dripline to divert increased moisture flow away from an art panel. 	
		- Artificial reinforcement to improve the structural integrity of a feature.	
Safety hazard Site access control, signage, stabilisatio techniques		Measures to address safety hazards will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan, such as:	
		- Signage to warn persons accessing the area of safety hazard.	
		- Construction of barriers to restrict access to unsafe areas.	
		- Road works to maintain road safety.	

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B		Page 26
Document ID: Land Management Plan		

Table 8
Potential Management Measures – Steep Slopes and Land in General

Environmental	Potential Management Measures		
Consequence	Measure	Description	
Impacts on surface water quality	Erosion and sediment control techniques	 Implementation of erosion and sediment control measures, such as: Installation of sediment fences downslope of erosion areas. Stabilisation of erosion areas using rock or other appropriate materials. Other erosion and sediment control measures consistent with 	
Impacts on flora, fauna, and/or their habitats	Erosion and sediment control techniques	 relevant guidelines. Implementation of erosion and sediment control measures, such as: Installation of sediment fences downslope of erosion areas. Stabilisation of erosion areas using rock or other appropriate materials. Other erosion and sediment control measures consistent with relevant guidelines. 	
	Remediation of surface tension crack	Permanent filling of the surface tension crack. The nature and extent of the in-fill material (e.g. sand) determined in consultation with the landholder. Methods of in-filling may include manual application or use of small machinery (e.g. bob cat).	
Aboriginal heritage	Salvage of artefacts, aesthetic repair	Aboriginal heritage management measures will be implemented in accordance with the Metropolitan Coal Longwall 304 Heritage Management Plan, such as: Establishing an artificial support between the roof and floor, known as standing supports. Installation of an artificial dripline to divert increased moisture flow	
		away from an art panel. - Artificial reinforcement to improve the structural integrity of a feature.	
Safety hazard	Site access control, signage, stabilisation techniques	 Measures to address safety hazards will be implemented in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan, such as: 	
		 Signage to warn persons accessing the area of safety hazard. Construction of barriers to restrict access to unsafe areas. Road works to maintain road safety. 	

9 CONTINGENCY PLAN

One cliff and overhang site (COH17) has been identified within 600 m of Longwall 304 secondary extraction.

In the event the subsidence impacts observed exceed the land performance measure detailed in Section 5 of this LMP, Metropolitan Coal will implement the following Contingency Plan:

- The observation will be reported to the Manager Technical Services and/or the Environment & Community Superintendent within 24 hours.
- The observation will be recorded in the Land Management Plan Subsidence Impact Register (Appendix 2).
- Metropolitan Coal will report any exceedance of the land performance measure to the DP&E and WaterNSW as soon as practicable after Metropolitan Coal becomes aware of the exceedance.
- Metropolitan Coal will assess public safety and where appropriate implement safety measures in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan.

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page 27		
Document ID: Land Management Plan		

- Metropolitan Coal will assess impacts on known Aboriginal heritage sites and where appropriate implement measures in accordance with the Metropolitan Coal Longwall 304 Heritage Management Plan.
- Metropolitan Coal will assess the impacts on the aesthetic values of the land feature.
- Metropolitan Coal will assess the environmental consequences of the subsidence impacts, in consultation with relevant specialists and WaterNSW, including:
 - a review of potential impacts on surface water quality in accordance with the Metropolitan
 Coal Longwall 304 Water Management Plan; and
 - a review of potential impacts on flora, fauna, and their habitats in accordance with the Metropolitan Coal Longwall 304 Biodiversity Management Plan.

This will include an assessment of the environmental consequences and how they compare to the assessment of environmental consequences in the Project EA and Preferred Project Report.

- Metropolitan Coal will conduct an investigation to evaluate the potential contributing factors in consultation with WaterNSW. The investigation will:
 - include the re-survey of relevant subsidence monitoring lines;
 - compare and critically analyse measured versus predicted subsidence parameters;
 - review measured subsidence parameters against the observed impact; and
 - review the subsidence monitoring program and update the program where appropriate.
- Metropolitan Coal will identify an appropriate course of action with respect to the identified impact(s), in consultation with specialists and relevant agencies including WaterNSW, as necessary. For example:
 - proposed contingency measures;
 - a program to review the effectiveness of the contingency measures; and
 - consideration of adaptive management under circumstances where a water resource or watercourse performance measure detailed in Table 1 of the Project Approval has been exceeded.

Contingency measures will be developed in consideration of the specific circumstances of the cliff instability (e.g. the location, nature and extent of the impact) and the assessment of environmental consequences in consultation with WaterNSW. Potential contingency measures include management measures described in Tables 7 and 8.

The proposed course of action will consider the nature and extent/scale of all recorded cliff falls. It may, for example, be more appropriate to remediate previous cliff fall areas as opposed to the specific cliff fall that initiated the implementation of the Contingency Plan.

- Metropolitan Coal will submit the proposed course of action to the DP&E for approval.
- Metropolitan Coal will implement the approved course of action to the satisfaction of the DP&E.
- In accordance with Condition 6, Schedule 6 of the Project Approval, Metropolitan Coal will provide a suitable offset to compensate for the impact to the satisfaction of the Secretary of the DP&E if either the contingency measures implemented by Metropolitan Coal have failed to remediate the impact or the Secretary determines that it is not reasonable or feasible to remediate the impact.

A Contingency Plan Check List has been developed and is provided in Appendix 3.

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page 28		
Document ID: Land Management Plan		

10 FUTURE EXTRACTION PLANS

In accordance with Condition 7, Schedule 3 of the Project Approval, Metropolitan Coal will collect baseline data for the next Extraction Plan (i.e. Longwall 305 on).

Cliffs COH11, COH12 and COH13 (Figures 2 and 4) have been identified by MSEC (2008) adjacent to the Woronora Reservoir over Longwalls 307 and 308. Baseline data has been obtained for Cliffs COH11, COH12 and COH13 including:

- photographic records of each cliff and overhang;
- sketches of overhangs; and
- mapping of the approximate location of the cliff/overhang face and the rear extent of the overhang/undercut.

The detailed baseline information for each site is included in Appendix 1 with the baseline data observed for sites COH1, COH2, COH3, COH4, COH5, COH6, COH6A, COH7, COH8, COH9, COH10, COH14, COH15, COH16, and COH17.

Baseline data collection for the next Extraction Plan will also include a description of steep slopes and land in general and a description of the recorded subsidence impacts (i.e. where mining of Longwalls 303 or 304 has resulted in subsidence impacts overlying the next Extraction Plan longwall layout [if any] at the time of Extraction Plan preparation).

Consideration of the environmental performance and management measures of this LMP will also inform the appropriate type and frequency of monitoring of the land features relevant to the next Extraction Plan.

11 ANNUAL REVIEW AND IMPROVEMENT OF ENVIRONMENTAL PERFORMANCE

In accordance with Condition 3, Schedule 7 of the Project Approval, Metropolitan Coal will conduct an Annual Review of the environmental performance of the Project by the end of March each year.

The Annual Review will specifically address the environmental performance of the LMP and will:

- describe the works that were carried out in the past calendar year, and the works that are proposed to be carried out over the next calendar year;
- include a comprehensive review of the monitoring results and complaints records of the Project over the past year, including a comparison of these results against the:
 - relevant statutory requirements, limits or performance measures/criteria;
 - monitoring results of previous years; and
 - relevant predictions in the Project EA, Preferred Project Report and Extraction Plan;
- identify any non-compliance over the last year, and describe what actions were (or are being) taken to ensure compliance:
- identify any trends in the monitoring data over the life of the Project;
- identify any discrepancies between the predicted and actual impacts of the Project, and analyse the potential cause of any significant discrepancies; and

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page 29		
Document ID: Land Management Plan		

• describe what measures will be implemented over the next year to improve the environmental performance of the Project.

As described in Section 2, this LMP will be reviewed within three months of the submission of an Annual Review, and revised where appropriate.

12 INCIDENTS

An incident is defined as a set of circumstances that causes or threatens to cause material harm to the environment, and/or breaches or exceeds the limits or performance measures/criteria in the Project Approval.

The reporting of incidents will be conducted in accordance with Condition 6, Schedule 7 of the Project Approval. Metropolitan Coal will notify the Secretary of the DP&E and any other relevant agencies of any incident associated with the Project as soon as practicable after Metropolitan Coal becomes aware of the incident. Within seven days of the date of the incident, Metropolitan Coal will provide the Secretary and any relevant agencies with a detailed report on the incident.

13 COMPLAINTS

A protocol for the managing and reporting of complaints has been developed as a component of Metropolitan Coal's Environmental Management Strategy and is described below.

The Environment & Community Superintendent is responsible for maintaining a system for recording complaints.

Metropolitan Coal will maintain public signage advertising the telephone number on which environmental complaints can be made. The Environment & Community Superintendent is responsible for ensuring that the currency and effectiveness of the service is maintained. Notifications of complaints received are to be provided as quickly as practicable to the Environment & Community Superintendent.

Complaints and enquiries do not have to be received via the telephone line and may be received in any other form. Any complaint or enquiry relating to environmental management or performance is to be relayed to the Environment & Community Superintendent as soon as practicable. All employees are responsible for ensuring the prompt relaying of complaints. All complaints will be recorded in a complaints register.

For each complaint, the following information will be recorded in the complaints register:

- date and time of complaint;
- method by which the complaint was made;
- personal details of the complainant which were provided by the complainant or, if no such details were provided, a note to that effect;
- nature of the complaint;
- the action(s) taken by Metropolitan Coal in relation to the complaint, including any follow-up contact with the complainant; and
- if no action was taken by Metropolitan Coal, the reason why no action was taken.

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page 30		
Document ID: Land Management Plan		

The Environment & Community Superintendent is responsible for ensuring that all complaints are appropriately investigated, actioned and that information is fed back to the complainant, unless requested to the contrary.

In accordance with Condition 10, Schedule 7 of the Project Approval, the complaints register will be made publicly available on the Peabody website and updated on a monthly basis. A summary of complaints received and actions taken will be presented to the Community Consultative Committee as part of the operational performance review.

14 NON-COMPLIANCES WITH STATUTORY REQUIREMENTS

A protocol for the managing and reporting of non-compliances with statutory requirements has been developed as a component of Metropolitan Coal's Environmental Management Strategy and is described below.

Compliance with all approvals, plans and procedures will be the responsibility of all personnel (staff and contractors) employed at or in association with the Metropolitan Coal Mine, and will be developed through promotion of Metropolitan Coal ownership under the direction of the General Manager.

The Manager – Technical Services and/or Environment & Community Superintendent will undertake regular inspections, internal audits and initiate directions identifying any remediation/rectification work required, and areas of actual or potential non-compliance.

As described in Section 12, Metropolitan Coal will notify the Secretary of the DP&E and any other relevant agencies of any incident associated with Metropolitan Coal as soon as practicable after Metropolitan Coal becomes aware of the incident. Within seven days of the date of the incident, Metropolitan Coal will provide the Secretary of the DP&E and any relevant agencies with a detailed report on the incident.

A review of Metropolitan Coal's compliance with all conditions of the Project Approval, mining leases and all other approvals and licences will be undertaken prior to (and included within) each Annual Review. The Annual Review will be made publicly available on the Peabody website.

Additionally, in accordance with Condition 8, Schedule 7 of the Project Approval, an independent environmental audit was undertaken by the end of December 2011, and is undertaken a minimum of once every three years thereafter. A copy of the audit report will be submitted to the Secretary of the DP&E and made publicly available on the Peabody website. The independent audit will be undertaken by an appropriately qualified, experienced and independent team of experts whose appointment has been endorsed by the Secretary of the DP&E.

15 REFERENCES

Department of Planning and Environment and NSW Trade & Investment – Division of Resources and Energy (2015) Guidelines for the Preparation of Extraction Plans Required under Conditions of Development Consents, Project Approvals and Mining Lease Conditions for Underground Coal Mining. Version 5. Draft.

Helensburgh Coal Pty Ltd (2008) Metropolitan Coal Project Environmental Assessment.

Helensburgh Coal Pty Ltd (2009) Metropolitan Coal Project Preferred Project Report.

Metropolitan Coal Pty Ltd (2012) Metropolitan Coal 2012 Annual Review.

Metropolitan Coal – Land Management Plan		
Revision No. LMP-R01-B Page 31		
Document ID: Land Management Plan		

- Metropolitan Coal Pty Ltd (2014) *Metropolitan Coal 2013 Annual Review and Annual Environmental Management Report.*
- Metropolitan Coal Pty Ltd (2016) Metropolitan Coal 2015 Annual Review.
- Metropolitan Coal Pty Ltd (2017) Metropolitan Coal Six Monthly Report, 1 January to 30 June 2017.
- Mine Subsidence Engineering Consultants (2008) Metropolitan Colliery Longwalls 20-44 Subsidence Assessment Report (MSEC Report MSEC285 Revision C, August 2008), Appendix A in HCPL (2008) Metropolitan Coal Project Environmental Assessment.
- Mine Subsidence Engineering Consultants (2019) Metropolitan Mine Longwall 304 Subsidence Predictions and Impact Assessments for the Natural and Built Features in Support of the Extraction Plan (MSEC Report MSEC1009).
- Operational Risk Mentoring (2019) *Metropolitan Coal Longwall 304 Environmental Risk Assessment Report.*
- SP Solutions (2008) *Metropolitan Coal Project Environmental Risk Analysis*. Appendix O in the HCPL (2008) *Metropolitan Coal Project Environmental Assessment*.


Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B		Page 32	
Document ID: Land Management Plan			


APPENDIX 1	
BASELINE MAPPING AND PHOTOGRAPHS – CLIFFS AND OVERHANGS	
BASELINE MAPPING AND PHOTOGRAPHS – CLIFFS AND OVERHANGS	
BASELINE MAPPING AND PHOTOGRAPHS – CLIFFS AND OVERHANGS	
BASELINE MAPPING AND PHOTOGRAPHS – CLIFFS AND OVERHANGS	
BASELINE MAPPING AND PHOTOGRAPHS – CLIFFS AND OVERHANGS	

Metropolitan Coal – Land Management Plan

Revision No. LMP-R01-B Document ID: Land Management Plan

Metropolitan Coal – Land Management Plan





Site COH1 Photographic Record



Photo C1-01 View from opposite bank at the western end



Photo C1-02 View from opposite bank





Photo C1-04 Low overhang



Photo C1-05 Low overhang



Photo C1-06 Low overhang






Photo C1-08 Northern end of cliff




Photo C1-09 Cliff ~9m high, Overhang ~6m high and ~4m deep




Photo C1-10 Cliff ~9m high, Overhang ~6m high and ~4m deep





Photo C1-12 Cliff ~9m high, overhang ~6m high and ~4m deep




Photo C1-13 Overhang ~5m high, ~3m deep with additional 2m undercut



Photo C1-14 Overhang ~5m high, ~3m deep with additional 2m undercut



Photo C1-15 Southern end of cliff




Photo C1-16 Southern end of cliff




Photo C1-17 Southern end of cliff/Northern end of large overhang



Photo C1-18 Northern end of large overhang




Photo C1-19 Large overhang looking north




Photo C1-20 Large overhang looking south




Photo C1-21 Overhang height ~6m,total overhang depth ~14m






Photo C1-23 Large overhang looking south




Photo C1-24 Large overhang looking north



Photo C1-25 Large overhang looking north



Photo C1-26 Large overhang looking south






Photo C1-28 Large overhang looking south




Photo C1-29 Large overhang looking north



Photo C1-30 Southern end of overhang, height ~2m, depth ~6m



Photo C1-31 Southern end of overhang, height ~2m, depth ~6m


Level 1, 228 Victoria Ave, Chatswood NSW 2067
PO Box 3047, Willoughby North NSW 2068
Tel +61 2 9413 3777 Fax +61 2 9413 3822
www.minesubsidence.com



HELENSBURGH COAL
METROPOLITAN COLLIERY
LONGWALLS 23-27
CLIFF No. COH2

DATE: 23-July-2013 DRAWING No: Rev No
MSEC487-08 Map02 01

Site COH2 Photographic Record






Photo C2-02 Northern end of overhang, height ~4m, depth ~3.5m



Photo C2-03 Northern end of overhang, height ~4m, depth ~3.5m



Photo C2-04 Underside of overhang, height ~4m, depth ~3.5m




Photo C2-05 Beneath overhang looking south




Photo C2-06 Northern end of main overhang




Photo C2-07 Looking south, overhang height ~6m, depth ~3m



Photo C2-08 Looking south, overhang height ~6m, depth ~3m



Photo C2-09 Looking north, overhang height ~6m, depth ~3m




Photo C2-10 Southern end of main overhang



Photo C2-11 Rock ledge between overhangs, ~7.5m high



Photo C2-12 Overhang, height ~1.5m, depth ~3m





Photo C2-13 Outside face of overhang



Photo C2-14 Overhang, height ~1.5m, depth ~3m






Photo C2-16 Overhang, height ~1.5m, depth ~3m



Photo C2-17 Overhang, height ~1.5m, depth ~3m



Photo C2-18 Overhang, height ~1.5m, depth ~5m



Photo C2-19 Overhang, height ~1.5m, depth ~5m



Photo C2-20 Between overhangs



Photo C2-21 Between overhangs



Photo C2-22 Overhang, height ~2.2m, depth ~6m





Photo C2-23 Overhang, height ~2.2m, depth ~6m, looking at southern end



Photo C2-24 Overhang, height ~2.2m, depth ~6m



Site COH3 Photographic Record




Photo C3-01 View from opposite bank




Photo C3-02 View from centre of Waratah Rivulet



Photo C3-03 Southeast end of overhang, height ~3m to ~5m, depth ~7m




Photo C3-04 Southeast end of overhang, height ~3m to ~5m, depth ~7m



Photo C3-05 Below overhang looking south east




Photo C3-06 Below overhang looking south east



Photo C3-07 Below overhang looking south east



Photo C3-08 Below overhang looking north west



Photo C3-09 Below overhang looking north west



Photo C3-10 Below overhang looking west




Photo C3-11 Below overhang looking south east



Photo C3-12 Below overhang looking south east



Photo C3-13 Below overhang looking south east



Photo C3-14 Below overhang looking north west, height ~1.6m, depth ~4m to ~5m



Photo C3-15 North west end of overhang looking south east



Photo C3-16 North west end of overhang, tributary flows over top of overhang



Photo C3-17 Above the north west end of the overhang

Site COH4 Photographic Record



Photo C4-01 View from Waratah Rivulet



Photo C4-02 View from Waratah Rivulet



Photo C4-03 Overhang, height ~6m, depth ~3m




Photo C4-04 Overhang, height ~6m, depth ~3m




Photo C4-05 Overhang depth ~1m, height ~10m



Photo C4-06 South eastern corner of COH4



Photo C4-07 Overhang, height \sim 6m, depth \sim 3m





Photo C4-08 Overhang depth ~1m, height ~10m



Photo C4-09 Overhang, height ~6m, depth ~3m



Site COH5 Photographic Record



Photo C5-01 View from Upstream end of Pool S Looking Downstream




Photo C5-02 View of Overhang Looking Upstream



Photo C5-03 Overhang, height ~2.5m, depth ~7m, Looking Upstream



Photo C5-04 Overhang, height ~2.5m, depth ~7m, Looking North



Photo C5-05 Overhang, height ~2.5m, depth ~7m, Looking Downstream

Site COH6 Photographic Record




Photo C6-01 View Looking Upstream



Photo C6-02 View Looking Downstream



Photo C6-03 View Looking Upstream



Site COH6A Photographic Record




Photo C6A-01 View Looking South East




Photo C6A-02 Cliff, Maximum Height ~13m, Overhang Depth ~3m



Photo C6A-03 Cliff, Maximum Height ~13m, Overhang Depth ~3m




Photo C6A-04 Cliff, Maximum Height ~13m, Overhang Depth ~3m



Photo C6A-05 Cliff, Maximum Height ~13m, Overhang Depth ~3m



Photo C6A-06 Seepage Downstream from Cliff



Site COH7 Photographic Record




Photo C7-01 View Looking Downstream




Photo C7-02 Eastern End Looking South East



Photo C7-03 Eastern End Looking Upstream



Photo C7-04 Overhang, Looking Upstream



Photo C7-05 Overhang depth ~10, Looking Downstream



Photo C7-06 Overhang, Looking Upstream




Photo C7-07 Overhang Looking Downstream




Photo C7-08 Cross Bedded Strata at Back of Overhang



Photo C7-09 Overhang Looking Upstream





Photo C7-11 Overhang ~ 3m Depth



Photo C7-12 Overhang ~7m Depth





Photo C7-13 Western End of Overhang Looking Upstream



Photo C7-14 Western End of Overhang Looking Downstream



Site COH8 Photographic Record



Photo C4-01 Eastern End Looking Downstream



Photo C4-02 Eastern End Looking Upstream



Photo C4-03 Eastern End Looking Upstream



Photo C4-04 Overhang, ~6.5m, Looking Downstream



Photo C4-05 Overhang, ~6.5m, Looking Upstream



Photo C4-06 Back of Overhang



Photo C4-07 Western End Looking Downstream



Photo C4-09 Western End Looking Upstream

Level 1, 228 Victoria Ave, Chatswood NSW 2067 PO Box 3047, Willoughby North NSW 2068 Tel +61 2 9413 3777 Fax +61 2 9413 3822 www.minesubsidence.com



HELENSBURGH COAL
METROPOLITAN COLLIERY
LONGWALLS 23-27
CLIFF No. COH9

DATE: 23-July-2013 DRAWING No: Rev No
MSEC487-08 Map11 01

Site COH9 Photographic Record




Photo C9-01 View Looking Downstream




Photo C9-02 View Looking West




Photo C9-03 Back of Overhang



Photo C9-04 Back of Overhang



Photo C9-05 View Looking Downstream

Site COH10 Photographic Record



Photo C10-01 View Looking Downstream



Photo C10-02 View Looking Downstream




Photo C10-03 View from Northern End Looking Upstream



Photo C10-04 Back of Overhang



Photo C10-05 Overhang ~5m Maximum Depth




Photo C10-06 Overhang ~5m Maximum Depth



Photo C10-07 Overhang ~5m Maximum Depth




Photo C10-08 View Looking Upstream




Photo C10-09 View Looking Upstream




Photo C10-10 Overhang Looking Downstream



Photo C10-11 View Looking Upstream




Photo C10-12 View Looking Downstream



Photo C10-13 View Looking Upstream




Photo C10-14 View Looking Downstream






Photo C10-16 Overhang ~3m Maximum Depth



Photo C10-17 View Looking North West

mine subsidence

Tel +61 2 9413 3777 www.minesubsidence.com



HELENSBURGH COALMETROPOLITAN COLLIERY LONGWALL 304

CLIFF No. COH11

MSEC1009 - Map13

1 Mar 2019

01

Site COH11 Photographic Record




Photo C11-01 Western End Looking North West



Photo C11-02 Eastern End Looking North West

Site COH12 Photographic Record



Photo C12-01 View Looking North West



Photo C12-02 View Looking North West



Photo C12-03 View Looking Downstream



Photo C12-04 View Looking Upstream

Suite 402, 13 Spring Street, Chatswood NSW 2067 PO Box 302, Chatswood NSW 2057 Tel +61 2 9413 3777 msec mine subsidence



HELENSBURGH COAL METROPOLITAN COLLIERY LONGWALL304 CLIFF No. CHO13

1 Mar 2019

MSEC1009 - Map15 01

Site COH13 Photographic Record



Photo C13-01 View Looking East



Photo C13-02 View Looking North East



Photo C13-03 South End Looking Upstream



Photo C13-04 South End Looking Downstream





Photo C13-05 North End Looking Upstream



Photo C13-06 North End Looking Downstream



Site COH14 Photographic Record



Photo C14-01 Western end of COH14



Photo C14-02 Detached blocks at western end of COH14



Photo C14-03 Detached blocks at western end of COH14




Photo C14-04 Detached blocks at western end of COH14



Photo C14-05 Rock face ~8m high




Photo C14-06 Cliff ~10m to ~15m high



Photo C14-07 From top of cliff looking west




Photo C14-08 Looking at south east side of COH14



Photo C14-09 Western side of COH14




Photo C14-10 Overhang, height ~4m, depth ~1.5m to ~3m



Photo C14-11 Overhang, height ~4m, depth ~1.5m to ~3m



Photo C14-12 Looking west to overhang, height ~4m, depth ~1.5m to ~3m




Photo C14-13 Overhangs, height ~3m, depth ~1.5m to ~3m




Photo C14-14 Overhangs, height ~3m, depth ~1.5m to ~3m



Photo C14-15 Rock ledges uphill of COH14, height ~5m to ~7m



Photo C14-16 Rock ledges uphill of COH14, height ~5m to ~7m





Photo C14-17 Rock ledges uphill of COH14, height ~5m to ~7m



Site COH15 Photographic Record



Photo C15-01 Eastern End Looking Upstream




Photo C15-02 Eastern End Looking Upstream



Photo C15-03 Eastern End – Existing Fracture in Rock



Photo C15-04 Top of Cliff Looking East




Photo C15-05 Top of Cliff Looking East





Photo C15-06 Western End Looking Downstream



Photo C15-07 Western End Looking Downstream






Photo C15-09 View Looking Downstream



Photo C15-10 View Looking Downstream



Photo C15-11 View of Overhang – Maximum ~3m depth



Photo C15-12 View of Overhang – Maximum ~3m depth





Photo C15-13 Cliff Maximum height ~16m






Photo C15-15 View Looking Upstream




Photo C15-16 View Looking Upstream







Photo C15-18 View Looking Upstream



Photo C15-19 View Looking North West Towards Cliff



Site COH16 Photographic Record



Photo C16-01 View Looking Downstream



Photo C16-02 Southern End Looking Upstream




Photo C16-03 Southern End Back of Overhang



Photo C16-04 Overhang Looking Upstream




Photo C16-05 Overhang Looking Downstream



Photo C16-06 View Looking Upstream






Photo C16-08 View Looking Downstream



Photo C16-09 View Looking Downstream



Photo C16-10 Overhang Looking Upstream



Photo C16-11 Overhang Looking Upstream



Photo C16-12 View Looking Upstream



Photo C16-13 View Looking Downstream

Suite 402, 13 Spring Street, Chatswood NSW 2067 PO Box 302, Chatswood NSW 2057 Tel +61 2 9413 3777 msec mine subsidence www.minesubsidence.com



HELENSBURGH COAL METROPOLITAN COLLIERY LONGWALL304 CLIFF No. CHO17

DATE: 1 Mar 2019 MSEC1009 - Map16

DRAWING No:

Rev No 01

Site COH17 Photographic Record



Photo C17-01 North West End Looking North East



Photo C17-02 Central Area Looking North East



Photo C17-03 South Eastern End Looking North East



Photo C17-04 South Eastern End Looking North East



Photo C17-05 View Looking Downstream




Photo C17-06 View Looking Upstream




Photo C17-07 View Looking Downstream




Photo C17-08 View Looking Upstream



Photo C17-09 View Looking Downstream



Photo C17-10 View Looking Upstream



Photo C17-11 View Looking Downstream

APPENDIX 2

LAND MANAGEMENT PLAN SUBSIDENCE IMPACT REGISTER AND ASSESSMENT FORM

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B				
Document ID: Land Management Plan				

Land Management Plan - Subsidence Impact Register

Impact Register Number ¹	Land Feature ²	General Impact Description ³	Length of Recorded Cliff Instability ⁴	Cumulative Length of Recorded Cliff Instability ⁵	Does the Impact Exceed the Land Performance Measure? (Yes/No) ⁵	Management or Contingency Measures Implemented? (Yes/No) ⁶	Were Measures Effective? (Yes/No) ⁷
1	Fire Road	Surface tension crack on Fire Road 9C situated adjacent to the ribline of Longwall 20 (between survey pegs C20 and C21).	N/A	N/A	N/A	No	N/A
		Approximately 10 m long, with maximum width of 20 mm.					
2	Rock Ledge	Rock ledge collapse on the Unnamed Tributary.	N/A	N/A	N/A	No	N/A
3	Cliff	Vertical tension crack on the cliff face of site COH2 along with a small rock fall.	1.5 m	1.5 m	No	No	N/A
		Tension crack was 50 mm x 15 m and the rock fall was approximately 1.5 m long, 0.5 m wide and approximately 0.5m^3 .					
		No water seepage was observed.					
4	Rock Ledge	Rock ledge collapse at Pool TB-M on Tributary B.	N/A	N/A	N/A	No	N/A
5	Rock Ledge	Surface cracking and rock fall at a rock ledge located over Longwall 23B.	N/A	N/A	N/A	No	N/A
6	Rock platform	Surface cracking on rock platform.	N/A	N/A	N/A	No	N/A
7	Rock ledge	Rock fall from rock ledge.	N/A	N/A	N/A	No	N/A

Notes:

- 1: Fill out all details in the Subsidence Impact Register Assessment Form and record the register number here.
- 2: Land feature (e.g. cliff face, overhang, steep slope, ridgetop, fire road, etc.).
- 3: General impact description (e.g. cliff instability, surface tension crack, rock ledge collapse, etc.).
- 4: Length of recorded cliff instability (i.e. freshly exposed rock face evident and debris scattered around the base of the cliff or overhang).
- 5: If the cumulative length of cliff instabilities equals or exceeds 3% of the total length of cliffs (and associated overhangs) within the mining area, notify General Manager. If less than 3%, notify the Manager Technical Services or Environment & Community Superintendent of the cumulative length.
- 6: Indicate whether management or contingency measures were implemented (yes or no).
- 7: Indicate whether the implemented management or contingency measures were considered to be effective (yes or no).

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B				
Document ID: Land Management Plan	·			

Land Management Plan – Subsidence Impact Register Assessment Form

Date:
Observer (Name and position):
Register Number (ie. Number 1, 2, etc.):
Longwall Number and Chainage:
Location of Observed Impact: (Examples: location of cliff instability in relation to the cliff face or overhang, location of surface tension crack in relation to fire trails, include GPS co-ordinates and a sketch)
Description of Observed Impacts
Description of Observed Impact: (Examples: nature and extent of cliff instability, length of cliff instability [i.e. freshly exposed rock face evident and debris scattered around the base of the cliff or overhang], other relevant aspects such as water seepage, approximate dimensions of surface tension cracks (length, width, depth), orientation of surface tension cracks, dimensions of rock falls (e.g. rock ledges that occur along the Waratah Rivulet), any other relevant information, attach photographs)

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B				
Document ID: Land Management Plan				

Description of Potential Environmental Consequences:

Examples:
- the nature and extent of impacts on the aesthetic values of the land feature;
- areas of erosion or sedimentation that have the potential to impact on surface water quality;
- the co-ordinates of the subsidence impact to assess impacts on known Aboriginal heritage sites;
- nature and extent of impacts on potential flora and fauna habitats;
- evidence of impacts on terrestrial fauna (e.g. observed fauna mortality);
- impacts on the serviceability of fire trails and/or stream crossings
- any other relevant information
Attach photographs
· · · · · · · · · · · · · · · · · · ·
Description of Photographs:

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B			
Document ID: Land Management Plan			

Person Notified:	Environment & Community Superintendent	
	Manager – Technical Services	
	General Manager	
	Schola Managor	_
Actions Required:	Management Measures	
	Contingency Plan Initiated	
	Incident Notification	
	Safety Measures/Public Safety	
	Management Plan Requirements	
	sures Implemented:	
Contingency Meas	sures Implemented:	
Effectiveness of C	ontingency or Management Measures	3:

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B			
Document ID: Land Management Plan			

APPENDIX 3 CONTINGENCY PLAN CHECK LIST

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B				
Document ID: Land Management Plan				

Contingency Plan Check List

Contingency Plan Component	Yes/No	Comment
Observation reported to the Manager – Technical Services or the Environment & Community Superintendent (within 24 hours).		
Observation recorded in the Land Management Plan – Subsidence Impact Register.		
Reporting of any land performance measure exceedance to DP&E and WaterNSW (as soon as practicable after Metropolitan Coal becomes aware of the exceedance).		
Assessment of public safety and where appropriate implementation of safety measures in accordance with the Metropolitan Coal Longwall 304 Public Safety Management Plan.		
Assessment of impacts on known Aboriginal heritage sites and where appropriate implementation of measures in accordance with the Metropolitan Coal Longwall 304 Heritage Management Plan.		
Assessment of impacts on the aesthetic values of the land feature.		
Assessment of the environmental consequences in consultation with relevant specialists, including:		
impacts on surface water quality in accordance with the Metropolitan Coal Longwall 304 Water Management Plan; and		
impacts on flora, fauna, and their habitats in accordance with the Metropolitan Coal Longwall 304 Biodiversity Management Plan.		
Assessment to compare environmental consequences with assessment of environmental consequences in the EA.		
Conduct investigation to evaluate the potential contributing factors. Investigation to;		
include the re-survey of relevant subsidence monitoring lines;		
compare and critically analyse measured versus predicted subsidence parameters;		
review measured subsidence parameters against the observed impact; and		
review the Subsidence Monitoring Program and update the program where appropriate.		

Metropolitan Coal – Land Management Plan				
Revision No. LMP-R01-B				
Document ID: Land Management Plan				

Contingency Plan Check List (Continued)

Contingency Plan Component	Yes/No	Comment
Identification of appropriate course of action with respect to the identified impact(s) in consultation with specialists and relevant agencies. For example:		
proposed contingency measures;		
a program to review the effectiveness of the contingency measures; and		
consideration of adaptive management under circumstances where a water resource or watercourse performance measure outlined in Table 1 of the Project Approval has been exceeded.		
Submission of the proposed course of action to the DP&E for approval.		
Implementation of the approved course of action to the satisfaction of the DP&E.		
Provision of a suitable offset - if either the contingency measures implemented by Metropolitan Coal have failed to remediate the impact or the Secretary determines that it is not reasonable or feasible to remediate the impact.		

Metropolitan Coal – Land Management Plan			
Revision No. LMP-R01-B			
Document ID: Land Management Plan			