

APPENDIX 2 – EXPLORATION

2016 Summary of Exploration Activities

LEASE	HOLE_ID	EAST	NORTH	HTD	HRD
ML1573	2016P2W_01	770766.1	6417165.9	Rotary open or non core hole	Structure
ML1573	2016P2W_02	770807.3	6417101.8	Rotary open or non core hole	Structure
ML1573	2016P2W_03	770812.6	6417040.5	Rotary open or non core hole	Structure
ML1573	2016P2W_04	770816	6416987.7	Rotary open or non core hole	Structure
ML1573	2016P2W_05	770819.8	6416942.8	Rotary open or non core hole	Structure
ML1573	2016P2W_06	770909.6	6417184.2	Rotary open or non core hole	Structure
ML1573	2016P2W_07	770913.3	6417135.8	Rotary open or non core hole	Structure
ML1573	2016P2W_08	770916.2	6417093.3	Rotary open or non core hole	Structure
ML1573	2016P2W_09	770919.5	6417037.5	Rotary open or non core hole	Structure
ML1573	2016P2W_10	770925.9	6416987.1	Rotary open or non core hole	Structure
ML1573	2016P2W_11	770929.7	6416935.9	Rotary open or non core hole	Structure
ML1573	2016P2W_12	770852.6	6417159.4	Rotary open or non core hole	Structure
ML1573	2016P2W_13	770859	6417117.2	Rotary open or non core hole	Structure
ML1573	2016P2W_14	770864.4	6417059.5	Rotary open or non core hole	Structure
EL6169	PW1163	769947.6	6420446	Coal Cored	Coal quality testing and analysis
EL6169	PW1164	772986.2	6420124.9	Coal Cored	Coal quality testing and analysis
EL6169	PW1164A	772988.2	6420125.9	Partially cored hole	Redrill - coal quality
ML1573	PW1165	767605.8	6420416.8	Coal Cored	Coal quality testing and analysis
EL7091	PW1166	776002.7	6417505.5	Coal Cored	Coal quality testing and analysis
EL7091	PW1167	775082.3	6418070.8	Coal Cored	Coal quality testing and analysis
ML1573	PW1168	769196.6	6417724.6	Coal Cored	Coal quality testing and analysis
ML1573	PW1169	774213.1	6416182.9	Coal Cored	Coal quality testing and analysis
ML1573	PW1170	774135.4	6416840.3	Coal Cored	Coal quality testing and analysis
ML1573	PW2122	773886.2	6419448.6	Rotary open or non core hole	Intrusion investigation
ML1573	PW2123	773905.2	6419449.6	Rotary open or non core hole	Intrusion investigation
ML1573	PW2124	773920.9	6419449.8	Rotary open or non core hole	Intrusion investigation
ML1573	PW2125	773864.9	6419450.3	Rotary open or non core hole	Intrusion investigation
ML1573	PW2126	773865.1	6419470.5	Rotary open or non core hole	Intrusion investigation
ML1573	PW2127	773875.9	6419431.3	Rotary open or non core hole	Intrusion investigation
ML1573	PW2128	773893.7	6419430.1	Rotary open or non core hole	Intrusion investigation
ML1573	PW2129	773895.1	6419470.3	Rotary open or non core hole	Intrusion investigation
ML1573	PW2130	773893.8	6419489.3	Rotary open or non core hole	Intrusion investigation
ML1573	PW2131	773894.5	6419509	Rotary open or non core hole	Intrusion investigation
ML1573	PW2132	773912.6	6419618.1	Rotary open or non core hole	Intrusion investigation
ML1573	PW2133	773907.5	6419594.1	Rotary open or non core hole	Intrusion investigation
ML1573	PW2134	773866.5	6419484.1	Rotary open or non core hole	Intrusion investigation
ML1573	PW2136	773645.1	6418792.5	Rotary open or non core hole	Intrusion investigation
ML1573	PW2137	773638.9	6418780	Rotary open or non core hole	Intrusion investigation
ML1573	PW2138	773633	6418765.3	Rotary open or non core hole	Intrusion investigation
ML1573	PW2139	773630.1	6418749.1	Rotary open or non core hole	Intrusion investigation
ML1573	PW2140	773625.9	6418735.7	Rotary open or non core hole	Intrusion investigation