WILPINJONG COAL PTY LTD

COMMUNITY COMPLAINTS REGISTER SUMMARY

from

1 January 2026 to 31 July 2026

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
03 Jan 2026 at 8:59 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
03 Jan 2026 at 9:01 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
07 Jan 2026 at 9:08 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
08 Jan 2026 at 9:47 AM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
21 Jan 2026 at 10:32 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
24 Jan 2026 at 6:08 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise around 10 PM last night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
26 Jan 2026 at 9:42 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
26 Jan 2026 at 9:48 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise and to obtain information about equipment operating locations. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff, but information requested by the Caller was provided.
27 Jan 2026 at 3:03 PM	Ringwood Road, Wollar	Blast, overpressure	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about blast noise. WC staff investigated the complaint and determined that a blast had occurred at WC and that the overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were compliant. The Caller declined to speak to WC staff.
31 Jan 2026 at 9:44 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
6 Feb 2026 at 9:32 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
18 Feb 2026 at 9:47 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
18 Feb 2026 at 10:07 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
19 Feb 2026 at 9:22 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
13 Mar 2026 at 8:17 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
25 Mar 2026 at 8:51 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
26 Mar 2026 at 9:01 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
31 Mar 2026 at 8:45 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
6 Apr 2026 at 1:30 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
6 Apr 2026 at 2:11 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing noise all night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
6 Apr 2026 at 9:26 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing noise during the day. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
15 Apr 2026 at 8:51 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing mine noise during the morning. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
15 Apr 2026 at 9:07 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
15 Apr 2026 at 9:11 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
19 Apr 2026 at 7:59 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing truck noise during the morning. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
27 Apr 2026 at 9:31 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. WC staff spoke to the caller the following day as requested to discuss their complaint.
7 May 2026 at 8:14 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about machinery noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. WC staff spoke to the Caller about their complaint.
8 May 2026 at 9:08 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing mine noise during the night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
30 May 2026 at 7:58 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about hearing mine noise during the night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
30 May 2026 at 10:09 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
04 Jun 2026 at 3:41 PM	Ringwood Road, Wollar	Blast, overpressure	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about a loud blast. WC staff investigated the complaint and determined that a blast had occurred at WC and that the overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were compliant. WC staff spoke to the Caller about their complaint.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
13 Jun 2026 at 11:01 AM	O'Briens Crossing, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
14 Jun 2026 at 10:47 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about loud noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
14 Jun 2026 at 11:08 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
16 Jun 2026 at 10:03 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to make a noise complaint. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
17 Jun 2026 at 10:27 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. WC staff spoke to the Caller about their complaint.
24 Jun 2026 at 5:11 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about dust from Pit 8. WC staff investigated the complaint and determined that dust emissions from Pit 8 operations were being effectively managed and remained compliant with applicable requirements. WC staff attempted to speak to the Caller about their complaint.

2026
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
02 Jul 2026 at 3:19 PM	Wollar Village Community Hall	Blast, overpressure & vibration	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about a loud blast. WC staff investigated the complaint and determined that a blast had occurred at WC and that the overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were compliant. The Caller declined to speak to WC staff.
04 Jul 2026 at 2:15 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
04 Jul 2026 at 9:27 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise during the night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
21 Jul 2026 at 11:19 AM	Mogo Road, Wollar	Blast, overpressure & vibration	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to enquire if WC had a blast. WC staff investigated the complaint and determined that a blast had occurred at WC and that the overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were compliant. The Caller declined to speak to WC staff.
24 Jul 2026 at 3:52 AM and 5:21 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal (**WC**) to complain about mine noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.