



**WILPINJONG COAL PTY LTD**

**COMMUNITY COMPLAINTS REGISTER  
SUMMARY**

**from**

**1 January 2021 to 30 April 2021**

**2021  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
03 Jan 2021 at 9:26 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about an odour coming from WC over the past week. WC staff investigated the complaint and were unable to identify any odour that would account for the Caller's complaint. The wind direction for most of that period was from the East and so the Caller was upwind of WC. The Caller declined to speak to WC staff.
05 Jan 2021 at 9:09 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about an odour coming from WC. WC staff investigated the complaint and were unable to identify any odour that would account for the Caller's complaint. The wind direction at that time was from the North-West, which was not towards the Caller. The Caller declined to speak to WC staff.
06 Jan 2021 at 12:44 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
09 Jan 2021 at 9:07 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about an odour coming from WC. WC staff investigated the complaint and were unable to identify any odour that would account for the Caller's complaint. The wind direction at that time was from the East and so the Caller was upwind of WC. The Caller declined to speak to WC staff.
16 Jan 2021 at 07:54 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about truck noise from WC during the night. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria during that period. The Caller declined to speak to WC staff.
18 Jan 2021 at 12:48 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about truck noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria at that time. The Caller declined to speak to WC staff.

## 2021 Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
18 Jan 2021 at 02:13 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria at that time. The Caller declined to speak to WC staff.
20 Jan 2021 at 12:18 PM	Ringwood Road, Wollar	Blast	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about hearing a blast. WC staff investigated the complaint and confirmed that the blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. The Caller declined to speak to WC staff.
23 Jan 2021 at 07:37 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about dust from Pit 8 at WC. WC staff investigated the complaint and confirmed actions were being taken to control dust. The Caller declined to speak to WC staff.
28 Jan 2021 at 03:53 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about dust from Pit 8 at WC. WC staff investigated the complaint and confirmed operations were being carried out to control dust in strong wind conditions. The Caller declined to speak to WC staff.
28 Jan 2021 at 9:54 PM	Cooyal Lane, Cooyal	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Wollar Village were below the Noise Criteria at that time. WC staff spoke to the Caller about their complaint.
01 Feb 2021 at 8:56 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about an odour coming from WC. WC staff investigated the complaint and were unable to identify any odour that would account for the Caller's complaint. The wind direction at that time was from the East and so the Caller was upwind of WC. The Caller declined to speak to WC staff.
05 Feb 2021 at 9:45 PM	Cooyal Lane, Cooyal	Noise	Mobile Phone	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Wollar Village were below the Noise

**2021  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				Criteria. WC staff spoke to the Caller about their complaint.
12 Feb 2021 at 9:22 AM	Barnett Street, Wollar Village	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels from mining operations were being managed below the Noise Criteria. WC staff attempted to speak to the Caller about their complaint, but the Caller declined.
21 Feb 2021 at 10:17 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
22 Feb 2021 at 1:20 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about machinery noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
22 Feb 2021 at 10:33 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
25 Feb 2021 at 9:30 AM	Barnett Street, Wollar Village	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels from mining operations were being managed below the Noise Criteria. WC staff attempted to speak to the Caller about their complaint, but the Caller declined.
26 Feb 2021 at 4:51 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about dust coming from WC. WC staff investigated the complaint and confirmed that dust was being appropriately managed onsite. The Caller declined to speak to WC staff.
01 Mar 2021	Mogo Road, Wollar	Noise	Telephone Complaints	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff

**2021  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
at 10:27 AM			Line	investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
01 Mar 2021 at 11:00 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
13 Mar 2021 at 12:50 PM	Barigan Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about truck and mine noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Wollar Village were below the Noise Criteria. The Caller declined to speak to WC staff.
18 Mar 2021 at 10:19 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
23 Mar 2021 at 4:24 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
10 Apr 2021 at 9:13 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal ( <b>WC</b> ) to complain about noise from WC. WC staff investigated the complaint and confirmed that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.