



WILPINJONG COAL PTY LTD

**COMMUNITY COMPLAINTS REGISTER
SUMMARY**

from

1 January 2022 to 31 May 2022

2022
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
08 Jan 2022 at 10:40 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria ¹ . The Caller declined to speak to WC staff.
11 Jan 2022 at 5:44 PM	Mogo Road, Wollar	Blast – Overpressure & Vibration	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about blast overpressure and vibration from WC. WC staff investigated the complaint and confirmed that no blast event occurred at WC on that day. The Caller declined to speak to WC staff.
11 Jan 2022 at 7:53 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
25 Jan 2022 at 4:13 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about truck and mine noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
06 Feb 2022 at 10:11 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
14 Feb 2022 at 8:08 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC during the night. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
20 Feb 2022 at 9:09 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels

**2022
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
20 Feb 2022 at 10:09 AM	Mogo Road, Wollar	Noise & Blast	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC and a blast at WC the day before. WC staff investigated the complaint and determined that: (i) the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria; and (ii) the recorded overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were also compliant. The Caller declined to speak to WC staff.
21 Mar 2022 at 8:30 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC over the weekend. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
22 Mar 2022 at 4:04 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about airborne dust from WC 24 hours earlier. WC staff investigated the complaint and confirmed that the PM10 dust levels recorded in the community for the time reported were constant and well below the 24-hour PM10 dust limit of 50 ug/m3. The Caller could not be contacted about their complaint.
23 Mar 2022 at 10:42 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
28 Apr 2022 at 12:18 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about a blast from WC. WC staff investigated the complaint and determined that there was no blasting carried out at WC. WC staff spoke to the Caller about their complaint.
28 Apr 2022 at 12:33 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about a blast from WC. WC staff investigated the complaint and determined that there was no blasting carried out at

**2022
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				WC. The Caller declined to speak to WC staff.
28 Apr 2022 at 8:12 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about loud noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
29 Apr 2022 at 10:09 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
30 Apr 2022 at 12:20 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC during the morning. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
07 May 2022 at 9:00 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.
15 May 2022 at 10:41 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
15 May 2022 at 8:07 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.

2022
Community Complaints Register Summary

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
16 May 2022 at 4:01 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about airborne dust from the Pit 6 area as the Caller was driving past WC. WC staff investigated the complaint and determined that a blast had occurred in Pit 6 at 3:51 PM. The Caller declined to speak to WC staff.
16 May 2022 at 4:04 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about airborne dust from the Pit 6 area as the Caller was driving past WC. WC staff investigated the complaint and determined that a blast had occurred in Pit 6 at 3:51 PM. WC staff spoke to the Caller about their complaint.
18 May 2022 at 8:20 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria. The Caller declined to speak to WC staff.
19 May 2022 at 10:09 AM	Mogo Road, Wollar	Noise & Dust	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC and dust 'yesterday morning' from WC. WC staff investigated the complaint and determined that: (i) the low frequency (LF) noise levels recorded by the real-time noise monitor at Mogo Road were below the Noise Criteria; and (ii) the PM10 dust levels recorded in the community for 'yesterday morning' well below the 24-hour PM10 dust limit of 50 ug/m3. The Caller declined to speak to WC staff.
24 May 2022 at 7:59 AM	Mogo Road, Wollar	Spontaneous Combustion	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about signs of spontaneous combustion from the Pit 3 area as the Caller was driving past WC. WC staff investigated the complaint and determined that minor spoil heating was being managed and operations were compliant. The Caller declined to speak to WC staff.
30 May 2022 at 9:21 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.

**2022
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
30 May 2022 at 11:03 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller contacted Wilpinjong Coal (WC) to complain about excessive noise from WC. WC staff investigated the complaint and determined that the low frequency (LF) noise levels recorded by the real-time noise monitor at Ringwood Road were below the Noise Criteria. The Caller declined to speak to WC staff.

ⁱ Noise Criteria refers to the noise criteria in Condition 3, Schedule 3 of Development Consent (SSD-6764).