



**North Goonyella Mine – Bulletin  
November 21, 2018**

- Activities at the North Goonyella mine site are focused on assessment of underground conditions and advanced planning for re-ventilation ahead of potential re-entry to the mine when safe and appropriate to do so.
- Strict exclusion zones remain in place with underground access prohibited and limited access to surface areas of the mine.
- Peabody remains in regular contact with the Queensland Mines Inspectorate.
- Surface drilling to establish more monitoring bores is continuing, as is the use of underground camera images to assess underground conditions.
- Water management activities are being implemented in response to ongoing accumulation of water in parts of the mine.
- CO levels have been stable for weeks but remain slightly elevated. Site personnel are taking steps to monitor and isolate any potential source of elevated CO.
- Continue to use camera images; most have shown no effects while some have shown localized impacts in specific areas.
- The mobile GAG unit is on standby and will be mobilised back to Dysart when appropriate.
- All North Goonyella employees remain working on site, redeployed to other Peabody operations or on leave.
- The company's inquiry is continuing, and the company also is co-operating fully with the governmental investigation.