



**North Goonyella Mine – Bulletin
November 28, 2018**

- Activities at the North Goonyella mine site remain focused on assessment of underground conditions and advanced planning for re-ventilation ahead of potential re-entry to the mine when safe and appropriate to do so.
- Exclusion zones remain in place with underground access prohibited and limited access to surface areas of the mine.
- Peabody remains in regular contact with the Queensland Mines Inspectorate.
- Surface drilling to establish additional monitoring bores is nearing completion.
- The mobile GAG unit is now being returned offsite.
- Pumping activities are advancing in response to ongoing accumulation of water in parts of the mine.
- Use of cameras to assess underground conditions continues and has recorded images. Most images show no impacts. Signs of roof falls have been observed in several areas of the mine from the multiple areas observed to date. One section of the conveyor belt shows damage from the previously reported fire. CO levels in certain parts of the mine remain slightly elevated.
- The preparation plant is operating at low levels to re-process former prep plant material and produce limited quantities of thermal coal. A small amount of metallurgical coal remains onsite to be processed.
- The company's inquiry is continuing, and the company also is co-operating fully with the governmental investigation.