



WILPINJONG COAL PTY LTD

**COMMUNITY COMPLAINTS REGISTER
SUMMARY**

from

1 January 2018 to 31 July 2018

**2018
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
11 Feb 2018 at 10:54 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC) from 4:30AM to 11AM. WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant at that time period. WC staff spoke to the Caller by phone about their complaint.
13 Feb 2018 at 3:57 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC) around time of phone call. WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant at that time. WC staff spoke to the Caller by phone about their complaint.
25 Feb 2018 at 10:42 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant before complaint received. Caller declined to speak to WC staff.
26 Feb 2018 at 12:45 PM	Winchester Crescent, Cooks Gap	Blast	Telephone Complaints Line	Caller reported that they could hear a blast from Wilpinjong Coal (WC). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
01 Mar 2018 at 10:29 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant before complaint received. WC staff spoke to the Caller by phone about their complaint.
16 Mar 2018 at 1:14 PM	Ringwood Road, Wollar	Blast	Telephone Complaints Line	Caller reported that they heard a loud blast from Wilpinjong Coal (WC). WC staff investigated the complaint and determined: (i) that a blast at WC occurred at 12:30PM; and (ii) that the blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
16 Mar 2018	Mogo Road, Wollar	Dust	Telephone Complaints	Caller reported seeing dust from Wilpinjong Coal (WC). WC staff investigated the complaint to ensure operations were compliant. WC staff spoke to the Caller by

**2018
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
at 2:52 PM			Line	phone about their complaint.
18 Mar 2018 at 10:48 AM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller reported seeing dust from Wilpinjong Coal (WC). WC staff investigated the complaint to confirm operations were compliant. WC staff spoke to the Caller by phone about their complaint.
03 Apr 2018 at 10:34 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller complained about 'low frequency noise' from Wilpinjong Coal (WC). WC staff investigated the complaint and determined that the real-time low frequency (LF) noise levels recorded at Ringwood Road were compliant. The Caller declined to speak to WC staff.
05 Apr 2018 at 9:27 AM	Ringwood Road, Wollar	Visual Glare	Telephone Complaints Line	Caller complained about sunlight glare from 330Kv transmission tower recently installed. WC staff spoke to the Caller by phone about their complaint.
10 Apr 2018 at 10:43 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant. WC staff spoke to the Caller by phone about their complaint.
11 Apr 2018 at 4:15 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant. WC staff spoke to the Caller by phone about their complaint.
13 Apr 2018 at 3:51 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller reported seeing dust from Wilpinjong Coal (WC). WC staff investigated the complaint to confirm operations were compliant. WC staff spoke to the Caller by phone about their complaint.
17 Apr 2018 at 8:54 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller reported seeing dust from Wilpinjong Coal (WC) at 8:45 AM. WC staff investigated the complaint to confirm operations were compliant. WC staff spoke to the Caller by phone about their complaint.
25 Apr 2018 at 10:48 PM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant.

**2018
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				The Caller declined to speak to WC staff.
05 May 2018 at 11:38 AM	Winchester Crescent, Cooks Gap	Blast	Telephone Complaints Line	Caller reported that they could hear a blast from Wilpinjong Coal (WC). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
18 May 2018 at 10:13 AM	Mogo Road, Wollar	Blast	Telephone Complaints Line	Caller reported that they felt the overpressure of a blast from Wilpinjong Coal (WC). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
19 May 2018 at 9:24 PM	Cooyal Lane, Cooyal	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels were compliant. WC staff spoke to the Caller by phone about their complaint.
25 May 2018 at 9:21 PM	Cooyal Lane, Cooyal	Noise	Telephone Complaints Line	Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels were compliant. WC staff spoke to the Caller by phone about their complaint.
28 May 2018 at 2:18 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller reported seeing dust in Cumbo Valley. Wilpinjong Coal (WC) staff investigated the complaint to confirm operations were compliant. The Caller declined to speak to WC staff.
02 Jun 2018 at 3:00 PM	Winchester Crescent, Cooks Gap	Blast	Telephone Complaints Line	Caller reported that they could hear a 'big blast' from Wilpinjong Coal (WC). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
4 Jun 2018 at 3:00 PM	Barnett Street, Wollar Village	Odour	CCC Meeting	Representative reported at meeting that another resident had experienced unpleasant sensations from an odour they believed was from spontaneous combustion at

**2018
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				<p>Wilpinjong Coal (WC). The Representative said the odour was present on Sunday morning, June 3. WC staff investigated the complaint. On Sunday morning an employee from Wilpinjong Coal was outside their residence at Wollar Village at 7AM for about 1 hour and didn't smell any odour. The Representative also said they were on hold for 'quarter of an hour' trying to contact the Wilpinjong Coal telephone complaints line. The Supplier of the telephone complaints line was contacted and records supplied by the Supplier showed the longest wait time at the time the Representative said he couldn't get through was 94 seconds.</p>
07 Jun 2018 at 3:01 AM	Cooyal Lane, Cooyal	Noise	Telephone Complaints Line	<p>Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels were compliant. WC staff spoke to the Caller by phone about their complaint.</p>
10 Jun 2018 at 2:58 AM	Cooyal Lane, Cooyal	Noise	Telephone Complaints Line	<p>Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels were compliant. WC staff spoke to the Caller by phone about their complaint.</p>
10 Jun 2018 at 7:51 PM	Cooyal Lane, Cooyal	Noise	Wilpinjong mobile phone	<p>Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels were compliant. WC staff spoke to the Caller by phone about their complaint and also assisting the Caller with his concerns.</p>
11 Jun 2018 at 9:52 AM	Barnett Street, Wollar Village	Odour	Telephone Complaints Line	<p>Caller reported a 'bad smell' from Wilpinjong Coal (WC). WC staff attempted to contact Caller but Caller didn't return call. On that basis WC staff could not confirm any further details about the smell. A check of the mine site at that time found no odour issues.</p>
12 Jun 2018 at 10:02 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	<p>Caller reported hearing noise from Wilpinjong Coal (WC). WC staff confirmed that the real-time low frequency (LF) noise levels recorded at Mogo Road were compliant. WC staff spoke to the Caller by phone about their complaint.</p>
09 Jul 2018 at 11:31 AM	Winchester Crescent, Cooks Gap	Blast	Telephone Complaints Line	<p>Caller reported that they could hear a 'loud blast' from Wilpinjong Coal (WC). WC staff investigated the complaint. The blast overpressure and vibration levels</p>

**2018
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
				measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint.
12 Jul 2018 at 9:46 AM	Barnett Street, Wollar Village	Odour	Telephone Complaints Line	Caller reported an 'overpowering smell' coming from Wilpinjong Coal (WC). The Caller declined to speak to WC staff. A check of the mine site and Wollar Village at that time found no odour.
17 Jul 2018 at 9:32 AM	Barnett Street, Wollar Village	Noise	Telephone Complaints Line	Caller reported they could hear equipment noise from Wilpinjong Coal (WC). The Caller declined to speak to WC staff. WC staff investigated the complaint and found equipment already parked up to control noise levels. Stable atmospheric conditions present at that time. Further equipment parked up during morning to ensure noise levels at Wollar Village remained compliant.
24 Jul 2018 at 1:39 PM	Barnett Street, Wollar Village	Dust	Telephone Complaints Line	Caller reported 'dust' – presumably from Wilpinjong Coal (WC). The Caller declined to speak to WC staff. WC staff investigated the complaint and drove to Wollar Village. No visible dust was observed in the skyline over the WC Mine or Wollar Village.
27 Jul 2018 at 10:32 PM	Mogo Road, Wollar	Dust	Telephone Complaints Line	Caller reported seeing dust coming from Wilpinjong Coal (WC). WC staff investigated the complaint to confirm operations were compliant. WC staff spoke to the Caller by phone about their complaint.
31 Jul 2018 at 9:07 AM	Barnett Street, Wollar Village	Noise	Telephone Complaints Line	Caller reported noise from Wilpinjong Coal (WC). The Caller declined to speak to WC staff. WC staff investigated the complaint and confirmed that the real-time low frequency (LF) noise levels were compliant.