



## WILPINJONG COAL PTY LTD

## COMMUNITY COMPLAINTS REGISTER SUMMARY

from

1 January 2019 to 31 July 2019

2019 Community Complaints Register Summary

| Date and<br>Time           | From                              | Concern Raised | Received                     | Investigation and Action Taken   |
|----------------------------|-----------------------------------|----------------|------------------------------|--|
| 14 Jan 2019<br>at 11:49 AM | Mogo Road, Wollar                 | Blast          | Telephone Complaints<br>Line | Caller reported hearing a loud blast that occurred at Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. Caller declined to speak to WC staff.                               |
| 14 Jan 2019<br>at 12:10 PM | Mogo Road, Wollar                 | Blast          | Telephone Complaints<br>Line | Caller reported hearing a loud blast that occurred at Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. Caller declined to speak to WC staff.                               |
| 24 Jan 2019<br>at 9:03 PM  | Mogo Road, Wollar                 | Odour& Dust    | Telephone Complaints<br>Line | Caller reported in general terms odour and dust coming from Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint and found nothing to explain Caller's complaint. Caller declined to speak to WC staff.  |
| 31 Jan 2019<br>at 3:19 PM  | Mogo Road, Wollar                 | Blast          | Telephone Complaints<br>Line | Caller reported that they felt the vibration of a blast from Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint. |
| 09 Feb 2019<br>at 9:32 AM  | Barnett Street, Wollar<br>Village | Noise          | Telephone Complaints<br>Line | Caller reported noise from Wilpinjong Coal ( <b>WC</b> ). The Caller declined to speak to WC staff. WC staff investigated the complaint and confirmed that the real-time low frequency (LF) noise levels were compliant.   |
| 23 Mar 2019<br>at 11:37 AM | Barnett Street, Wollar<br>Village | Noise          | Telephone Complaints<br>Line | Caller reported noise from Wilpinjong Coal ( <b>WC</b> ). The Caller declined to speak to WC staff. WC staff investigated the complaint and confirmed that the real-time low frequency (LF) noise levels were compliant.   |
| 10 May 2019<br>at 3:39 PM  | Dry Creek Road,<br>Totnes Valley  | Blast          | Telephone Complaints<br>Line | Caller reported hearing a loud blast that occurred at Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and   |

2019 Community Complaints Register Summary

| Date and<br>Time           | From                     | Concern Raised   | Received                     | Investigation and Action Taken  |
|----------------------------|--------------------------|------------------|------------------------------|---|
|                            |                          |                  |                              | so compliant. WC staff spoke to the Caller by phone about their complaint.  |
| 10 Jul 2019<br>at 11:45 AM | Mogo Road, Wollar        | Blast            | Telephone Complaints<br>Line | Caller reported hearing a loud blast that occurred at Wilpinjong Coal ( <b>WC</b> ). WC staff investigated the complaint. The blast overpressure and vibration levels measured at the Environment Protection Licence (EPL) monitoring site were below EPL limits and so compliant. WC staff spoke to the Caller by phone about their complaint. |
| 16 Jul 2019<br>at 12:44 AM | Ringwood Road,<br>Wollar | Noise            | Telephone Complaints<br>Line | Caller reported hearing mine noise from Wilpinjong Coal ( <b>WC</b> ). The Caller declined to speak to WC staff. WC staff investigated the complaint and confirmed that the real-time low frequency (LF) noise levels were compliant.   |
| 16 Jul 2019<br>at 10:50 AM | Mogo Road, Wollar        | Tree Clearing    | Telephone Complaints<br>Line | Caller reported their concern about tree clearing that had occurred as part of approved mining operations at Wilpinjong Coal ( <b>WC</b> ). WC staff spoke to the Caller by phone about their complaint.  |
| 28 Jul 2019<br>at 7:52 AM  | Home Rule, NSW           | Driver Behaviour | Telephone Complaints<br>Line | Caller reported their concern about a group of vehicles that past the Caller on Ulan Road near Ulan Coal Mine. Caller believed the vehicles may have been going to Wilpinjong Coal ( <b>WC</b> ). WC staff spoke to the Caller by phone and investigated their complaint.   |