## APPENDIX 4 REHABILITATION & LAND MANAGEMENT


## 2023 Rehabilitation Photographic Register

Please refer to **Figure 4A** for locations of photographs and **Table 4A** and **Table 4B** for the 2023 Rehabilitation Photographic Register.

**Notes:** Previous annual photos of rehabilitation activities provide an historical account of the performance of primarily cover crops, until the performance and completion criteria for BVT and Regent Honeyeater habitat relevant to the Mine's rehabilitation areas was approved on the 24 April 2019 (**Table 4A**).

WCPL are in the process of establishing new photographic monitoring points in select rehabilitated areas of the mine (**Table 4B**).



















































<u>Peabody</u>

















































## Table 4B Rehabilitation Photographic Register (BVTs)

