



**WILPINJONG COAL PTY LTD**

**COMMUNITY COMPLAINTS REGISTER  
SUMMARY**

**from**

**1 February 2026 to 28 February 2026**

**2026  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
03 Jan 2026 at 8:59 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
03 Jan 2026 at 9:01 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
07 Jan 2026 at 9:08 PM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
08 Jan 2026 at 9:47 AM	Mogo Road, Wollar	Odour	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about an odour. WC staff investigated the complaint and found no odour source on site that would account for the resident's complaint. The Caller declined to speak to WC staff.
21 Jan 2026 at 10:32 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
24 Jan 2026 at 6:08 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise around 10 PM last night. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
26 Jan 2026 at 9:42 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

**2026  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
26 Jan 2026 at 9:48 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise and to obtain information about equipment operating locations. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff, but information requested by the Caller was provided.
27 Jan 2026 at 3:03 PM	Ringwood Road, Wollar	Blast, overpressure	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about blast noise. WC staff investigated the complaint and determined that a blast had occurred at WC and that the overpressure and vibration levels recorded at the EPL monitoring site at Wollar Village were compliant. The Caller declined to speak to WC staff.
31 Jan 2026 at 9:44 AM	Mogo Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Mogo Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
6 Feb 2026 at 9:32 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
18 Feb 2026 at 9:47 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.
18 Feb 2026 at 10:07 PM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.

**2026  
Community Complaints Register Summary**

Date and Time	From	Concern Raised	Received	Investigation and Action Taken
19 Feb 2026 at 9:22 AM	Ringwood Road, Wollar	Noise	Telephone Complaints Line	Caller messaged Wilpinjong Coal ( <b>WC</b> ) to complain about noise. WC staff investigated the complaint and determined that the low frequency noise levels recorded by the Ringwood Road real-time noise monitor were compliant with the Noise Criteria. The Caller declined to speak to WC staff.